

Mercedes-Benz W164, W251 and X164 (new ML, R, GL) DTBs

sales designation	model	engine	sales designation	model	engine
ML350 4MATIC	164.186	272.967	R350 4MATIC	251.165	272.967
ML500 4MATIC	164.175	113.964	R500 4MATIC	251.175	113.971
ML63 AMG 4MATIC	164.177	156.980	R63 AMG 4MATIC	251.177	156.980
ML320 CDI 4MATIC	164.122	642.940	R320 CDI 4MATIC	251.122	642.950
ML550 4MATIC	164.172	273.963	R350	251.156	272.967
ML320 CDI BlueTEC	164.125	642.820	R320 CDI BlueTEC	251.125	642.870
ML350	164.156	272.967	R350 CDI BlueTEC	251.124	642.870/950
ML450 4MATIC HYBRID	164.195	272.973			
ML350 CDI BlueTEC	164.124	642.820			
GL450 4MATIC	164.871	273.923	G500	463.249	113.962
GL320 CDI 4MATIC	164.822	642.940	G55 AMG	463.246	113.982
GL550 4MATIC	164.886	273.963	G55K AMG	463.271	113.993
GL320 CDI BlueTEC	164.825	642.820	G550	463.237	273.969
GL350 CDI BlueTEC	164.824	642.820			

Issue Date	DTB Number	Title
May 2009		For updates and full text subscribe at STAR TekInfo Since most initial bugs seem to be resolved now, there wont be further updates on this page.
May 07, 2009	S-B-01.30/23a	Revision: Warranty (Model Indicators) Information Updated All Passenger and Light Truck Models Equipped with Engine M272 / 273 Oil Seepage from Back of Cylinder Head
May 06, 2009	S-B-32.22/78a	Revision: WIS Document Reference Added (211.2) All Model 164, 211, 219, 221 and 251 Vehicles Equipped with Airmatic Suspension (Sales Code 489) "Airmatic - Visit Workshop" Displayed Within Instrument Cluster
May 06, 2009	S-B-18.20/43	All AMG Models Equipped with M156 Engine Engine Oil Leak at Oil Filter Housing Revision: Warranty Information Updated - Op Code 02-3472 Included Model 164.122/175/186, Model 171.454/456/473, Model 203.052/054/056 Model 209.356/375/456/475, Model 211.056/070/256, Model 215.375 Model 219.375, Model 220.170/175, Model 230.475, Model 251.122/165/175 Equipped with 7G-Tronic Transmission (NAG2), Serial Numbers Between 7229xx 00 327088 and 7229xx 00 338693 Transmission in Limp Home Mode with Fault Codes 2200, 2201, 2767 and 2768
May 05, 2009	S-B-27.50/59g	All Model 164, 211, 219 and 251 Vehicles, MY 2006 - MY 2008 All Model 221 Vehicles, MY 2007 - 2009 Equipped with Hands-free Telephone System and Dealer Retrofit iPod Interface Kit iPhone/iPhone 3G Music is Audible During an Active Phone Call
May 01, 2009	S-B-01.20/24a	Revision: Warranty Information Updated Model 164.177 Model 204.077 Model 209.377/477 Model 211.077/277 Model 216.377 Model 219.377 Model 221.177 Model 230.470 Model 251.177 Equipped with M156 Engine, Up to Engine Number 15698x 60 022000 Whistling Sound from Engine Compartment
Apr 30, 2009	S-B-82.70/68b	MY2005 to Present, Models All Telephone and Bluetooth Adapter Diagnosis and Test Tool W203 589 07 63 00 and Warranty Return Requirements
Apr 29, 2009	S-B-83.30/74o	Applicable Models (216 Added), Local Purchase and Warranty Information Updated All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Air Conditioning Musty/Moldy Odor Complaints
April 28, 2009	S-B-98.00/13P	Revision P: Approved Products Added MY-All All Models MBUSA-Approved Refinishing Products
April 24, 2009	2009030003	Recall: Model 164, Model Year 2009 Reposition Power Lift Gate Control Module and Replace Right and Left Tail Lamp Unit Seals
April 23, 2009	S-B-03.30/08i	Revision: Applicable Models Updated / Technical Content Revised Model 164.172/186/871/886, Model 171.454/456 Model 203.052/054/056/087/092, Model 204.054/056/061 Model 209.356/372/456/472 Model 211.056/072/087/090/256/287, Model 216.371, Model 219.372 Model 221.171/186, Model 230.471, Model 251.156/165 Equipped with M272 Engine or M273 Engine Check Engine Light On / Fault Codes Current and/or Stored in ME-SFI Control Module / Oil Leaking at Camshaft Adjustment Solenoid
Apr 22, 2009	T-B-72.20/59d	Revision: VIN Information within Warranty Table Corrected All Model 164 and 251 Vehicles Message "Liftgate Open" in Instrument Cluster Display or Liftgate Will Not Engage Completely
Apr 17, 2009	S-B-82.85/615b	Revision: Operation Code Typo Corrected Model 164.122/172/175/177/186, up to Model Year 2008 Model 203.052/054/056/076/087/092, up to Model Year 2007 Model 204.054/056/081, up to Model Year 2008 Model 209.356/372/377/456/472/477, up to Model Year 2008 Model 251.122/156/165/175/177, up to Model Year 2008 Equipped with COMAND Head Unit (Code 512, 527, 530, 528) Central Display Opening/Closing Errors or Inoperative, Voice Control Does Not Respond To User's Commands (Hands-free Conversation) and/or Other Party May Not Hear Driver's Conversation
Apr 16, 2009	T-B-47.10/55	Model 164.125/825, Model 251.125 Check Engine Light Illuminated with DTC 205C21
Apr 15, 2009	S-B-83.30/74n	Revision: Local Purchase Information Included for Wynns Part Number All Model 164, 171, 203, 204, 209, 211, 215, 219, 220, 221, 230 and 251 Vehicles Air Conditioning Musty/Moldy Odor Complaints
Apr 15, 2009	S-B-01.40/25a	Model 164.172/886 Model 209.372/472 Model 211.072/090 Model 216.371/386 Model 221.171/186 Model 230.471 Model 463.237 Equipped with M273 5.5L Engine Up to number D273.9xx 30 27007 (Approx. June 08) Coolant Loss
Apr 03, 2009	T-B-46.30/63b	Revision: Applicable Models Updated (164.156 Added) Model 164.156/172/186/871/886, Model 251.156/165 Power Steering Pump Noise
Apr 02, 2009	S-B-07.16/80d	Revision: Updated WIS Document Numbers Model 211.022/026, Model 164.122/822, Model 251.122 Work on Pressure Regulator Valve (as of CDI3, 1600 bar system)
Mar 31, 2009	T-B-54.21/204b	Revision: Notes Added (Page 2) Pertaining to Correct Parts Information Model 164.172/183/871/886, Up to VIN A360677 Model 251.156/165, Up to VIN A076568 Battery Not Charging and/or Vehicle Cranks Slow and/or Failed Alternator Test
Mar 26, 2009	T-B-82.35/606b	Revision: Remedy Updated All Model 164 / 251 Vehicles Windshield Washer System Inoperative After Front SAM Flash
Mar 24, 2009	T-B-83.00/81c	Revision: Damage Code Revised Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Malfunctions of Various Control Units and/or On-Board Power Supply Problems

Mar 23, 2009	T-B-54.10/178c	Revision: Damage Code Revised Model 164.122/125/172/175/177/186/822/825/871/886 Model 251.122/125/156/165/175/177 Message in Instrument Cluster: Battery Symbol and "Visit Workshop" in White
Mar 23, 2009	S-B-98.00/24	All Models, Paint Repairs
Mar 23, 2009	S-B-82.60/681a	Revision: Root Cause and Additional Diagnostic Information Added Model 164.122/125/172/175/177/186, Model 171.454/458/473/476 Model 211.022/056/072/077/087/090/277/287, Model 219.372/377 Model 230.470/471/472/477/479, Model 251.122/125/156/165, Model 463.237/271 All Model Year 2009 Equipped with Satellite Radio / HD Tuner Satellite Radio Not Available and "Device Unavailable" Displaying on the Head Unit May Cause Current Draw
Mar 23, 2009	T-B-65.10/05	Model 164.122/125/172/175/177/186/822/825/871/886 Indentations/Dings In The Roof Panel
Mar 23, 2009	P-B-83.00/109c	Revision: Parts List Updated to Include Heater Box Assembly as of April 6, 2009 All Model 163, 164, 170, 171, 199, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 240, 251 and 463 Vehicles Diagnostic Enhancement: Climate Control -- Enhanced Diagnostic Assistance Center "EDAC" for Repairs Under Warranty
Mar 20, 2009	S-B-82.70/475a	Revision: Applicable Models Updated All Passenger Car and Light Truck Models Telephone Calls Being Cut Off or Dropped
Mar 20, 2009	SCN CODING	Installation Bulletin Revision B MY2009 Model 164/251 and MY2010 Model X204 with Option Code 866 RSE Pre-Wiring Supplemental SCN and Variant Coding for COMAND and Rear Seat Entertainment System for WIS documents
Mar 20, 2009	2009020004	Revision to repair procedure regarding subscriber status in Subject E, step 6. Models 164/164.8/171/204/204.9/209/211/216/219/221/230/251 Model Years 2008 and 2009 Replace Tele Aid Control Module
Mar 19, 2009	S-B-91.40/130a	Revision: Parts Information Updated All Model 164, 171, 203, 209, 211, 219, 220, 221, 230 and 251 Seat Belt Does Not Roll Up Correctly
Mar 18, 2009	P-B-40.15/53a	Revised for All Models with TPMS and for One Time Use of Aluminum Valve Assembly MY-All, Models All with TPMS Notes on Tire Mounting/Dismounting with Tire Pressure Monitoring Systems
Mar 11, 2009	T-B-54.21/198f	Revision: Remedy 3 Added Model 164.122/172/177/186/822/871/886, 251.122/156/165, Model Year 2008 Battery Discharging - Increased Rest Current in the Rear SAM / CAN Bus Awake Mode Software in Steering column Module (SCM)
Mar 10, 2009	S-B-40.10/69	MY-All, Models All Radial Crack in Light Alloy Disk Wheel
Mar 10, 2009	S-B-83.55/118	All Passenger and Light Truck Models Defective Refrigeration Circuit / Refrigerant Compressor
Mar 08, 2009	T-B-54.10/216	MY- All, Models 164 and 251 Simplified Battery Replacement
Mar 06, 2009	T-B-77.20/78	Model 164.122/125/172/175/177/186/822/825/871/886 Glass Panel of Tilting/Sliding Roof Can Reverse During Automatic Closing
Mar 05, 2009	T-B-83.00/89c	Revision: Applicable Production Added to Remedy 1 Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Climate System Temperature Setting Not Possible / LED Indicator Does Not Change When Turning Temperature Selector Wheel
Feb 25, 2009	S-B-82.85/679	Model 164.122/125/172/175/177/186, Model 171.454/456/458/473 Model 211.056/065/072/077/087/090/277/287, Model 219.372/377 Model 230.470/471/472/477/479, Model 251.122/125/156/165, Model 463.237/271 All Model Year 2009, Equipped with Audio 20, Base Unit (COMAND without Navi) or COMAND Head Unit Radio Station Display Error, Telephone Bluetooth Connection Terminates, Various Navigation and System Errors
Feb 12, 2009	S-B-82.85/544a	Revision: Step 1 and Damage Type Updated Model 164.175/186/871, as of MY 06 Model 171.454/456/473, as of MY 05 - 08 with COMAND Head Unit Only Model 203.040/052/054/056/0...2/261/264/281/284/740/764, as of MY 05 - 07 Model 209.356/365/375/376/456/465/475/476, as of MY 05 - 08 Model 211.026/056/065/070/07...087/256/265/276/282/287, as of MY 04 - 08 Model 219.375/376, as of MY 06 - 08, Model 251.165/175, as of MY 06 Equipped with iPod Interface Kit iPod Intermittently Cannot Be Operated or Controlled Using Steering Wheel Controls, Delayed Response on Instrument Cluster Display, iPod Volume Too Low Compared to Other Audio Sources
Feb 11, 2009	S-B-54.21/215	All Models Equipped with Engine M272 and M273 Engine Cannot Be Started When Engine is Hot but Will Start After Engine has Cooled
Feb 05, 2009	S-B-67.00/25	MY-All, Models All New Window Glazing One-Component Adhesive Repair Kit
Feb 05, 2009	S-B-40.10/66	MY-All, Models All Approved Alkaline MB Wheel Cleaner for Light Alloy Disk Wheel
Feb 04, 2009	S-B-47.20/48b	Revision: Remedy Revised, All Models Equipped with Diesel Engines Check Engine Lamp Illuminated and Engine Will Not Start or Stalls After Starting at Low Ambient Temperatures (-15 C / 5 F)
Feb 04, 2009	S-B-46.50/34a	Models 164, 171, 203, 209, 211, 215, 216, 219, 220, 221, 230, 251 with code 213 (Speed Sensitive Power Steering - Parameter Steering) Speed Sensitive Power Steering (Parameter Steering) Malfunction
Jan 29, 2009	S-B-03.30/11	MY-All, Models All with Engine 272 with Transmission 722.6/9, Engine 273 with Transmission 722.9, Engine 272 with Transmission 722.6 Flywheel/Flexplate Replacement Procedure
Jan 29, 2009	S-B-40.15/65	MY-2001 - Present Models All (With Tire Pressure Monitoring System) Steel Valve Caps on Vehicles with Tire Pressure Monitoring Systems
Jan 28, 2009	S-B-54.10/213	MY-All, Models 164, 171, 199, 203, 204, 209, 211, 216, 219, 221, 230, 251, and 463 Battery Maintenance
Jan 28, 2009	T-B-83.00/124a	Revision: Note Added / Warranty Table Removed All Model 164 and 251 Vehicles No Air from Rear Center Outlets in Heating Mode
Jan 28, 2009	T-B-82.60/676	Model 164, 204 and 251 Vehicles, as of Model Year 2007 Diagnostic Enhancement: Rear Seat Entertainment System (RSE) Diagnostic Assistance Center "EDAC"
Jan 27, 2009	S-B-99.00/340	Distribution Notice, MY-All, Models All, Technical Data Manual for Passenger Cars, Edition 2008/2009
Jan 23, 2009	T-B-82.10/632b	Revision: Correct Pinout for 251 Model 164.122/125/172/175/177/186 Model 251.122/156/165/175/177 Stop/Tail Light Not Illuminating with 9102, 9103, 9106, 9107, 9126, 9127 or 9136
Jan 21, 2009	2008120011	Recall: Models 164/164.8/251, Model Year 2008 Replace Power Steering Rack (Approximately 577 vehicles are involved.)
Jan 20, 2009	T-B-14.40/27	Model 164.125/825, Model 251.125 Dosing Valve and Heated Line
Jan 20, 2009	S-B-83.55/126	Model 164.122/822, Model 211.022, Model 251.122 No Cooling Output / Refrigerant Compressor Malfunctioning

Jan 16, 2009	T-B-72.00/100c	<p>Revision: Note Added - Page 2 (mounting post) Model 164.122/172/175/177/186/822/871/886, as of VIN A298504 up to VIN A407859 Model 251.122/156/165 as of VIN A062281 up to VIN A083326 Equipped with Keyless Go (SA Code 889) Outside Door Handle No Longer Returns to End Position</p> <p>Revision: Applicable Models Updated (230 Added) Model 164.122/172/175/177/186/822/871/886, as of MY 2006 Model 171.454/456/473, as of MY 2006 Model 203.040/052/054/056/061/064/076/....264/281/284/740/764, as of MY 2005 Model 204.054/056/081, as of MY 2008 Model 209.356/365/372/375/376/377/456/465/472/475/476/477, as of MY 2005 Model 211.022/026/0...283/287 as of MY 2003 with COMAND Head Unit (528 or 530) Model 216.371/376/377/379, as of MY 2007 Model 219.372/377, as of MY 2007 Model 221.171/176/177/179/186, as of MY 2007 Model 251.122/156/165/175/177, as of MY 2006 Model 463.249/271, as of MY 2007 Equipped with iPod Interface System or Media Interface System (Option Code 518) Apple iPhone 3G or Newer iPod Generations Not Charging</p> <p>Model 251.122/125/156/165/175/177 Center Console Storage Compartment Crash Lock Triggered and Cannot be Unlocked</p> <p>All Model 164 / 203 / 209 Vehicles, as of Model Year 2005 All Model 171 / 251 Vehicles, as of Model Year 2006 All Model 204 Vehicles, as of Model Year 2008 All Model 211 Vehicles, as of Model Year 2004, Equipped with COMAND (528 or 530) All Model 216 / 219 / 221 / 463 Vehicles, as of Model Year 2007 Equipped with iPod Interface System or Media Interface System (Option Code 518) Various iPod Issues: iPod Battery Discharge, No Data Display, Slow Reaction When Listening to Audio Books</p> <p>MY-All, Models All, Replace Battery in Transmitter Key</p>
Jan 14, 2009	S-B-82.60/643a	
Jan 13, 2009	T-B-68.20/77	
Jan 07, 2009	S-B-82.60/629a	
Jan 05, 2009	S-B-80.00/53	
2008		
Dec 19, 2008	S-B-68.05/47a	<p>Revision: Applicable Models Expanded (all Passenger and Light Trucks) All Passenger and Light Truck Models Garage Door Opener Cannot be Programmed</p> <p>Revision: Applicable Models Revised (BlueTEC Vehicles Only) as of January 5, 2009 Model 164.125/825, Model 251.125 Equipped with OM642 Engine with BlueTEC Selective Catalytic Reduction (SCR) System Diagnostic Enhancement: OM642 Diesel Enhanced Diagnostic Assistance Center "EDAC"</p> <p>Revision: Production Cut-off Added to First Paragraph All 164, 171, 203, 209 and 251 Vehicles, Equipped with Memory Seats (Code 275) All 211, 219 and 230 Vehicles Easy Entry/Exit Feature for Seat Position Not Functioning</p> <p>Revision: Warranty Information Updated All Models Equipped with 722.9 (7G-Tronic) Transmission Transmission in Limp Home Mode</p> <p>Revision: Applicable Models Updated Model 164.175/186, Fuel Filler Flap Loose</p> <p>MY-All, Models 163, 164, 171, 203, 204, 209, 210, 211,... 221, 230, 251 Play in the Rack and Pinion Steering System</p> <p>Revision: Applicable Models Updated (251 Added) Model 164.122/172/175/177/186/822/866/871 Model 251.122/125/156/165/175/177 Water Sloshing Noise Under Instrument Panel</p> <p>All Model Vehicles Equipped with 722.9 Transmission- 7G-Tronic (NAG2) Hard 1-2 Shift and/or Hard Torque Converter Lockup Clutch Engagement</p> <p>MY-All, Models 164, 171, 203, 204, 209, 211, 216, 219, 221, 230, 251, and 463 (with Engine 272 or 273) Installing Air Filters</p> <p>Revision: Parts and Warranty Information Updated All Model 164 and 251 Chrome Plating Peeling on Decorative Caps on the Steering Wheel Spokes</p> <p>Revision: Content Updated, WIS Doc. Reference Included All Model 164 / 251 Vehicles Groaning/Cracking Noise When Steering</p> <p>Revision: Applicable Models Updated (Page 2 Chart) All Passenger and Light Truck Models, Flow Noises from Area of Power Steering Pump and/or Foaming of Power Steering Oil in Reservoir</p> <p>Model 164.122/172/175/177/186/822/871/886, MY 2006 - 2008 Model 171.454/456/473, MY 2005 - 2008 All Model 203 Vehicles, MY 2005 - 2008 (Except 203.065 and 203.747) All Model 209 Vehicles, MY 2005 - 2009 All Model 211 Vehicles, MY 2004 - 2008 with COMAND Head Unit (528 or 530) Model 216.371/376/377/379, MY 2007 - 2009 Model 219.372/377 2006 - 2008 Model 221.171/176/179/186/177 MY 2007 - 2009 Model 230.470/471/472/474/475/476/477/479 MY 2005 - 2008 Model 251.122/156/165/175/177 MY 2006 - 2008 Model 463.249/271, MY 2007 - 2008 Apple iPhone or iPhone 3G Address Book Not Loading In vehicles Equipped With Hands-free Telephone and Blue Tooth Cradle (HFP-Puck)</p> <p>Model 164.122/172/175/177/186 All Model 211 Vehicles, as of Model Year 2007 Xenon Burner Inoperative or Flickers</p> <p>Service Campaign: Models 164, 164.8, 251, Model Year 2008 Update Rear SAM Software</p> <p>Revision: Applicable Models Updated (Added 230 Equipped with M113 Engine) All Model 163, 203, 209, 211 and 220, Equipped with M112 Engine All Model 163, 164, 171, 203, 209, 211, 215, 219, 220, 230 and 251, with M113 Engine All Model 164, 171, 203, 209, 211 and 251 Equipped with M272 Engine All Model 164, 209, 211, 216, 219, 221 and 251 Equipped with M273 Engine All Model 164 and 251, Equipped with M272/273 Engine All Model 164, 211 and 251, Equipped with OM642 Engine All Model Years Replacement of Refrigerant Compressor Belt Pulley Due to Noise Complaints</p> <p>Revision: Content Revised, Software CD Part Numbers Included Model 164.122/125/172/175/177/186, Model Year 2009 Model 171.454/456/458/473, Model Year 2008 and 2009 Model 211.022/056/072/077/087/090/277/287, Model Year 2008 and 2009 Model 216.371/376/377/379/386, Model Year 2008 and 2009 Model 219.372/377, Model Year 2008 and 2009 Model 221.171/176/177/179/186, Model Year 2008 and 2009 Model 230.470/471/472/477/479, Model Year 2009 Model 251.125/156/165, Model Year 2009, Model 463.237/271, Model Year 2009 Equipped with COMAND Head Unit and Satellite Radio System COMAND Software Update Required to Subscribe to Additional SIRIUS XM Channels</p> <p>Revision: Complete Procedure Revised All Models Equipped with 7G-Tronic Transmission (NAG2) Uncomfortable Shift Quality of 1-2, 3-2 and 2-1 Gear Shifts</p>
Nov 26, 2008	S-B-46.30/40b	
Nov 24, 2008	S-B-82.70/666	
Nov 24, 2008	S-B-82.10/642	
Nov 21, 2008	2008110009	
Nov 20, 2008	S-B-83.55/87e	
Nov 20, 2008	S-B-82.60/640a	
Nov 20, 2008	S-B-27.60/61j	

Nov 20, 2008	T-B-88.70/62a	Revision: Applicable Models Updated Model 164.122/125/172/175/177/186/822/825/871/886 Model 251.122/125/156/165/175/177 Equipped with SA Code 500 (Electric Folding Outside Mirrors) Electric Folding for the Exterior Mirrors Not Functioning
Nov 19, 2008	SCN coding	Installation Bulletin Supplemental SCN and Variant Coding for COMAND/RSE MY2009, Model 251 and Model 164 with Option Code 866 RSE Pre-Wiring Supplemental SCN and Variant Coding for COMAND and Rear Seat Entertainment System for WIS documents
Nov 19, 2008	S-B-54.35/193a	Revision: Production Cut-Off Added All Passenger and Light Truck Models Up to April 2008 Production Replacing the Fanfare Horns
Nov 19, 2008	S-B-07.61/72a	Revision: Note on Page 2 Updated (Ignition Coil Statement) Model 129.068, Model 163.154/157/172/175, Model 164.172/175/186/871/886 [...], Model 251.156/165/175, Model 463.249 Diagnosis in DAS for Misfire Fault Codes
Nov 18, 2008	S-B-72.00/42g	Revision: Condition 2 Revised All Model 204, 164 and 251 Vehicles Door Seal Loose or Wind Noise from Door
Nov 14, 2008	T-B-27.00/111	Model 164.122/175/177/186/822/871/886 Throttle Lift-Off Clunking Noise In Vehicle Speed Range Up To Approx. 50 MPH
Nov 11, 2008	S-B-14.30/15e	Revision: Parts Note Added Model 163.154/157/172/174/175, Model 164.175/186, Model 170.465/466 [...], Model 251.156/165, Model 463.246/249/271, All Model Years Check Engine Light with DTC P2003, P2047, P0810 and P0814 Stored in Engine ECU
Nov 07, 2008	2008100007	Service Campaign: Model 251 with Engine OM 642, Model Year 2008 Install Exhaust Bracket Reinforcement at Transmission
Nov 06, 2008	S-B-07.00/84a	Revision: Content Revised All Models, Equipped with Engine M156, M272 and M273 Software Flash Requirements for ME 9.7 Control Units
Nov 05, 2008	S-B-91.10/112e	Revision: Technical Content Updated (Condition VIII Added) Model 164.122/172/175/177/186/822/886 Model 203.040/052/054/056/061/064/065...1/284/740/747/764 Model 209.356/365/372/375/376/377/456/465/472/475/476/477 Model 211.026/056/065/070/076/082/083/087/256/265/276/282/283/287 Model 219.375/376, Model 251.122/156/165/175/177 Front Seat Noise Complaints
Nov 04, 2008	S-B-27.00/109	All Models Equipped with Transmission 722.9- 7G-Tronic (NAG2), Model Year 2009 Delayed Engagement of Reverse Gear
Nov 04, 2008	S-B-91.16/179	All Model 164, 204, 209, 211, 219, 221 and 251 Vehicles Active Head Restraints Cannot be Reset
Nov 03, 2008	AN82.60-P-0013RT	Installation Bulletins, MY2009 Model 251 with Code 866 (Preinstallation for Rear Entertainment System) Retrofit for Rear Entertainment System
Nov 03, 2008	T-B-32.22/66c	Revision: Note Removed (pertaining to Airmatic Control Module) / Part Number Updated Model 164.122/172/175/177/186/822/871/886, Up to VIN A331395 Thumping Noises from Area of Front Axle on Rough Roads
Oct 30, 2008	T-B-82.60/478a	Revision: Damage Code Revised Model 164.175/186 Model Year 2006, Equipped with Rear Seat Entertainment System (RSES) No Audio Detected from Wireless Headphones, Display Will Not Power ON, Wavy or Flickering White Lines Through the LCD Display
Oct 30, 2008	S-B-00.00/80f	Revision: Applicable Models Updated (Model 164.871 Removed) Model 164.186, Up to Engine Serial No. 272 967 30 053879 Model 171.454/456, Up to Engine Serial No. 272 9xx 30 058705 Model 203.052/054/056/087/092, Up to Engine Serial No. 272 9xx 30 053555 Model 209.356/456, Up to Engine Serial No. 272 9xx 30 053555 Model 211.056/087/256/287, Up to Engine Serial No. 272 9xx 30 052208 Increased Engine Oil Consumption
Oct 30, 2008	S-B-82.10/598a	Revision: Parts Quantities Corrected to Match Information in Table / Note Added All Model 163, 164, 171, 203, 209, 211, 215, 219, 220, 230 and 251 Vehicles Replacing Exterior Light Bulbs
Oct 28, 2008	T-B-80.20/45a	Revision: Damage Code Revised Model 164.122/175/177/186/822/871 with SA Code 890 (Power Liftgate) Model 251.122/165/175/177 with SA Code 890 Power Liftgate Nonfunctional
Oct 28, 2008	S-B-18.00/40	Model 163, 164, 170, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251 and 463 AMG Vehicles, Equipped with Engine 112.96x, 113.98x, 113.99x, 156.98x or 275.98x Oil Consumption
Oct 27, 2008	S-B-13.22/01e	Revision: Work Instr. Pertaining to Spacer Revised / Diagram Included All Passenger and Light Truck Models Equipped with Engine M272 Up to Engine Number 272xxx 30 476520 Equipped with Engine M273 Up to Engine Number 273xxx 30 085890 Noise Coming From Front of Engine
Oct 24, 2008	S-B-18.00/37d	Revision: Damage Type Revised - Step 7 All Passenger and Light Truck Models Equipped with M156, M272, M273 or OM642 Engines Low Oil Level Symptoms
Oct 22, 2008	S-B-03.20/10	Model 211.022, Model 164.122/822, Model 251.122, Equipped with Engine OM642 Intermittent Knocking/Ticking Noise at Idle (with mp3 sound file to help diagnosis)
Oct 20, 2008	T-B-72.20/68a	Revision: Added Mobile Training Coach Link Model 164.871, Up to VIN A126315 with Code 890 (Power Tailgate) Power Tailgate Does Not Function Correctly
Oct 20, 2008	T-B-72.10/95a	Revision: Warranty Information Updated Model 251.122/156/165/175/177, Up to VIN A062280 Equipped with Infrared Reflecting Glass (Code 596) Laminated Side Window Glass Cracked
Oct 17, 2008	T-B-83.00/123	All Model 164 Vehicles, Produced up to 11/2005 Whistling Noises from Ventilation System
Oct 16, 2008	S-B-27.00/107a	Revision: Applicable Models and Warranty Info. Updated / SDS Flashing Info. Revised Model 164.122/822, Model 211.022, Model 251.122 Uncomfortable Shift Quality in Partial Load Ranges Affecting Upshifts 1-2, 2-3 and Downshifts 3-2, 2-1
Oct 16, 2008	S-B-49.00/12a	Revision: Damage Code Revised (Model 204 Only) Model 164.172/186/871/886, Model 171.454/456, 203.040/052/054/056/092/087/740 Model 204.054/056/081 Model 209.356/372/456/472 Model 211.056/072/087/090/256/287 Model 215.376/379 Model 216.371/376/379 Model 219.372 Model 220.176/179 Model 221.171/176/179/186 Model 230.471/476/477/479 Model 251.156/165 Engine Running Characteristics / Check Engine Light Activated
Oct 16, 2008	T-B-77.20/69	Model 164.122/125/172/175/177/186/822/825/871/886 Tilting/Sliding Roof Water Leakage At End Cap
Oct 15, 2008	T-B-99.00/337	Distribution Notice, Introduction into Service Manual MY2009, Engine 642.8 BlueTEC with AdBlue
Oct 14, 2008	S-B-82.60/638	All Models, as of Model Year 2008, Equipped with Satellite Radio Audio Interruptions/Mutes on Certain Satellite Radio Channels
Oct 09, 2008	T-B-91.16/177	Model 164.122/125/172/175/177/186/822/825/871/886 Model 251.122/125/156/165/172/175/177 Active Head Restraints Activate for No Reason

Oct 02, 2008	T-B-27.19/56d	Revision: Applicable Models Updated Model 164.122/125/175/177/186/822/825/871 Model 251.122/125/165/175/177 Automatic Transmission Remains in "P" Position
Oct 02, 2008	S-B-91.29/117a	Revision: Applicable Models Updated All Model 164 and 251 Vehicles All Model 211 Vehicles, MY 04 as of Production 19.2.04 and Later All Model 219, MY 07 and Later Replacement of Weight Sensing Seat Sensors
Oct 01, 2008	S-B-47.10/43a	Revision: Applicable Models Updated Model 164.122/125/822/825, Model 211.022, Model 251.122/125 Diesel Fuel Requirement for MY07 and Later Diesel Powered Vehicles
Oct 01, 2008	S-B-47.10/30d	Revision: Applicable Models Updated Model 164.122/125/822/825, Model 211.022/026, Model 251.122/125 Procedure for When Diesel Fuel Tank is Filled with Incorrect Type Fuel
Sep 26, 2008	S-B-18.00/17g	Revision: WIS Screenshots Added (Figures 1 and 2) All Passenger and Light Truck Models Equipped with FSS / FSS+ or MB Maintenance System Approved Service Products
Sep 26, 2008	2008050004	Revision to Warranty information, Repair Procedure, Parts information, and Quality Assurance Certificate, Models 164 and 164.8, Model Years 2006 - 2008 Rework Trailer Hitch
Sep 17, 2008	P-B-54.65/86a	Revision: Applicable Models Updated / Note Added on Page 2 (cause and remedy) All Models Equipped with Parktronic (SA Code 220) Erroneous Parktronic Activation
Sep 17, 2008	T-B-15.20/67	Model 164.122/822, Model 251.122 COMAND System Flickers or Switches Off Briefly, Fault Codes D011 and 9011 Displayed
Sep 16, 2008	S-B-82.30/634M	All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles Equipped with Rain/Light Sensor (SA Code 345) Auto On/Off Driving Lights and/or Rain/Light Sensor not Functioning Properly
Sep 10, 2008	AN82.60-P-0013GZ	Installation Bulletin MY2009, Model 164 with Code 866 (Rear Seat Entertainment System Prewiring) Retrofit for Rear Entertainment System
Sep 03, 2008	T-B-83.10/112a	Revision: Part Number Updated All Model 164 Vehicles, Water Entry into Vehicle Interior
Sep 02, 2008	S-B-80.57/24c	Revision: Note Updated All Model 164, 171, 203, 204, 209, 211, 219 and 251 Vehicles Diagnosis and Replacement of DAS3 Components (Key, EIS, ESL)
Aug 29, 2008	2008080001	Service Campaign: Models 164, 164.8, and 251 (with code 489) Model Years 2006-2008 Check Air Suspension Compressor and Replace if Necessary
Aug 28, 2008	T-72.00/66a	Revision: Applicable Models Updated Model 164.122/172/175/177/186/822/825/866, with Chrome Trim Model 164.871, Model 251.122/125/156/165/175/177, with Chrome Trim Corrosion Spots on Chrome Trim on Doors
Aug 27, 2008	2008070004	Service Campaign: Revision: Update to parts information and Work Procedure Model 251 with Diesel Engine OM 642, Model Years 2008 and 2009 Check Coolant Line, Replace if Necessary
Aug 22, 2008	S-B-00.40/89	MY- All, Models All with Transmission 722.6 or 722.9 Operating Fluid Specification Changes for Automatic Transmission (236.14)
Aug 21, 2008	S-B-82.60/633	All Model 164, 171, 203, 209, 211, 215, 216, 219, 220, 221, 230, 251 and 463 Vehicles Model Year 2004 to 2008 (excluding Model 204) WSG Pre-Authorization for Satellite Radio Receiver (SDAR)
Aug 21, 2008	T-B-72.10/65a	Revision: Applicable Models Updated (164.122/172/175/177/186 and all 251's Added) Model 164.122/172/175/177/186, Model 251.122/156/165/175/177 Aluminum Trim Strip on Interior Door Panels Makes a Creaking Noise
Aug 20, 2008	2006110005	Revision: Navi DVD part numbers updated, note added, revised in parts info Models 164, 171, 203, 209, 211, 215, 219, 220, 221, 230, 251, X164 Model Year 2005-2007 Install Software for Navigation System
Aug 19, 2008	S-B-97.30/05	MY-All Models All Corrosion Protection Without Hexavalent Chromium VI Model 129.066/067/068/076 Model 163.154/172/174/175/157 Model 164.175 Model 170.465/466 Model 171.473 Model 202.029 Model 203.061/064/076/081/084/261/264/281/284 Model 208.365/370/374/465/470 Model 209.365/375/376/465/475/476 Model 210.065/070/072/074/082/083/265/282 Model 211.065/070/076/082/083/265/276/282/283 Model 215.375 Model 220.067/070/083/170/173/174/175/183/184 Model 230.472/474/475 Model 251.175 Model 463.246/249/271 Tip Start Cycle Ending Prior to Engine Starting
Aug 15, 2008	T-B-77.20/65	Model 251.122/125/156/165/175/177 Top Sliding Roof Roller Blind Couplings Broken At Roller Blind
Aug 15, 2008	2008070002	Service campaign, Revision: Update to warranty information Models 164, 164.8, 171, 203, 209, 211, 216, 219, 221, 230, 251 with Engine 272 or 273 Model Years 2006-2007 Replace V-Belt Upper Guide Pulley
Aug 14, 2008	T-B-46.25/64	Models 164.172/186/871/886 Models 251.156/165 All Model Years Fluid Flow Noise from the Power Steering High Pressure Hose
Aug 13, 2008	T-B-98.10/18b	Revision: Content Added for Model 163 Vehicles All Model 163 and 164 Vehicles, Paint Damage on Tailgate
Aug 11, 2008	T-B-82.60/631	Model 164.122/172/175/177/186/822/871/886, as of Model Year 2006 Model 251.122/156/165/175/177, as of Model Year 2006 Equipped with Dealer Installed Rear Seat Entertainment System DVD Player not Recognizing US Region DVDs (Region 1)
Aug 04, 2008	S-B-82.85/627a	Revision: Warranty Policy Change as of August 15, 2008 All Model 164, 171, 211, 219, 230 and 251 Vehicles, Model Year 2009 Diagnostic Enhancement: NTG 2.5 Telematics Enhanced Diagnostic Assistance Center (EDAC)
Jul 30, 2008	2008070001	Recall: 164, 164.8, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251, 463 Model Years 2003-2009 Re-code the Software Calibration Number (SCN)
Jul 29, 2008	T-B-54.15/190a	Revision: Warranty Policy Change as of August 15, 2008 Model 164.122/172/175/177/186 Diagnostic Enhancement: Rear SAM Enhanced Diagnostic Assistance Center "EDAC"
Jul 29, 2008	S-B-82.30/366d	Revision: Note Pertaining to S-B-82.35/621 Added All Passenger Models All 164 / 251 Models, Adjusting Wiper Arms
Jul 28, 2008	S-B-91.60/171	Model 164.122/172/175/177/186/822/871/886 Model 211.065/070/072/076/077/082/083/087/090/256/265/276/277/282/283/287 Model 219.372/375/376/377 Model 251.122/156/165/175/177 Equipped with SA Code U10 Fault Code 9A14 Stored in Weight Sensing System (WSS) Control Module
Jul 28, 2008	T-B-68.20/76	Model 251.122/156/165, Front Armrest Storage Compartment Latches Stick
Jul 16, 2008	T-B-14.40/26	Model 164.122/822 Model 251.122 Check Engine Light Illuminated / DTCs 2306-002 and 2078-002
Jul 16, 2008	T-B-09.20/27b	Revision: Warranty Information Updated Model 164.177 Model 251.177 Up to Engine Type 156.98x 60005808 Check Engine Light On / Engine Shakes at Idle with Fault Codes 0745 and 0749

Jul 10, 2008	T-B-32.22/66	Model 164.122/172/175/177/186/822/871/886, Up to VIN A331395 Thumping Noises from Area of Front Axle on Rough Roads
Jul 09, 2008	S-B-98.30/22a	Revision: Tar Remover Solvent Information Added All Passenger Car and Light Truck Models Elimination of Adhesive Residues On Paint Work
Jul 02, 2008	T-B-33.30/23a	Revision: Reference to WIS Document Added Model 251.122/165/175/177, Up to VIN A049476 Rattling Noise in Area of Front Axle with Approx. 180 Degrees of Steering Wheel Input
Jul 01, 2008	S-SI-58/94e / 60/04e	MY-All (Including MY2009), Models All Dedicated Straightening Equipment for Collision Repair
Jun 25, 2008	S-B-00.20/88	All Model 164, 171, 211, 216, 219, 221 and 251 Vehicles Up to October 2006 Series Production Erroneous Maintenance Displayed Via ASSYST
Jun 17, 2008	S-B-07.16/69b	Revision: Note Updated Model 164.122/822, Model 211.022, Model 251.122 Engine Does Not Start or Runs Unevenly
Jun 16, 2008	T-B-72.10/95	Model 251.122/156/165/175/177, Up to VIN A062280 Equipped with Infrared Reflecting Glass (Code 596) Laminated Side Window Glass Cracked
Jun 16, 2008	T-B-72.00/73b	Revision: Content Revised Model 164.122/175/177/186/871, Model 251.122/165/175/177 Door Lock Knobs Jumping Up and Down
Jun 16, 2008	T-B-32.22/65	Model 164.122/172/175/177/186/822/871/886 Model 251.122/165/172/175/177 Discharge Noise from Airmatic Compressor
Jun 04, 2008	S-B-32.25/19e	Revision: Replacement Procedure & Applicable Models Updated All Model 124, 129, 140, 163, 164, 170, 171, 201, 202, 203, 208, 209, 210, 211, 215, 216, 219, 220, 221, 230, 251 and 463 Replacement Procedure of Shock Absorbers and Suspension Struts
Jun 04, 2008	T-B-72.00/93	Model 251.122/165/156/175/177, Up to VIN A079166 Creaking Noises in Area of Door Seal on Rough Roads
Jun 04, 2008	S-B-09.20/29	Model 164.122/822, Model 211.022, Model 251.122, Equipped with Engine 642 Oil Leak at the Engine Air Intake Duct
Jun 04, 2008	T-B-42.10/80b	Revision: Work Procedure for Front Axle and Parts Information Updated Model 164.122/175/177/186/822/871 Model 251.122/165/175/177 Model Year 2006 - 2007 Front / Rear Brakes Squeal When Braking
May 23, 2008	T-B-33.15/34a	Revision: Part Number Corrected Model 164.122/172/175/177/186/822/871/886, Model 251.122/156/165/175/177 Grunting / Creaking Noises from Area of Front Axle
May 23, 2008	T-B-91.22/152a	Revision: Symptom and Remedy Added Model 164.822/871/886, Inoperable / Noisy Third Row Seat Motor
May 22, 2008	S-SI-58.20/93f	Revision: AGA Fax and E-Mail Information Updated All MODELS, ORIGINAL, APPROVED PROTECTIVE COVERS FOR FENDERS, SEATS, AND FRONT AND REAR FASCIA
May 21, 2008	S-B-18.00/36a	Revision A: for Model Engines MY-All, All Models with Engines 111, 112, 113, 137, 271, 272, 273, 275, 285, 642, and 648 Display and Measurement of Engine Oil Level
May 21, 2008	S-B-82.35/621	MY-All, Models-All Windshield Washer System: Maintaining Wiping Quality and Controlling Noise
May 16, 2008	T-B-72.20/43f	Revision: Symptom and Remedy Updated Model 164.175/186 Model 251.165/175 Power Closing Assist on the Tailgate Intermittently Nonfunctional
May 15, 2008	S-B-49.10/11	MY-All, Models-All with Chrome Tail Pipe Finisher, The Care of Tail Pipe Finishers
May 09, 2008	T-B-91.12/148	Model 164.822/871, up to VIN A268285, Equipped with SA code 845 (3rd Row Seat Folding Down Electrically) and SA code 847 (3rd Row Seat with Folding Individual Seats) Easy Exit Strap for Second Row Seat Backrest Release Too Short
May 09, 2008	2008040003	Service campaign: Models 164 and 251 with Engine 156, Model Years 2007 - 2008 Recode Engine Type In ASSYST (Maintenance System) Control Module
May 03, 2008	S-B-40.10/60	MY-All, Models All, Nitrogen Use in Tire Inflation
May 02, 2008	S-B-58.30/45a	Revision: PMC Agreement (Page 3 and 4) Updated ALL MODELS, VEHICLE WHEEL ALIGNMENT EQUIPMENT COMPLIANCE
Apr 22, 2008	T-B-46.20/61a	Revision: Note Pertaining to Radial Play (Between Step 2 and 3) Revised All Model 164 / 251 Vehicles, Rattling / Thumping Noise on Rough Roads and/or Knocking Noise When Moving Steering in Both Directions
Apr 18, 2008	S-B-00.00/87	MY-All, Models All, General Overview of Documents in WIS-net and Locating Component Function Descriptions in WIS-net
Apr 15, 2008	S-B-68.30/75	All Passenger Car and Light Truck Models, Surface Damage Caused by Scent Dispenser
Apr 14, 2008	T-B-83.00/117	Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Incorrect Air Distribution or Temperature Control Malfunction of LIN bus / Teach-in Process of Actuator Motors not Possible DTC 9401, 9402, 9403, 9404, 9405, 9406, 9407, 9408, 9409, 9501, 9502, 9503 and 9505
Apr 11, 2008	S-B-14.40/25	Model 164.122, Up to VIN A277429, Model 211.022, Up to VIN B150432 Model 251.122, Up to VIN A060265 Engine Changes to Limp-Home Mode with DTC 2082-008
Apr 08, 2008	S-B-68.05/74	All Model 129, 140, 163, 164, 170, 171, 202, 203, 204, 208, 209, 210, 211, 215, 216, 220, 221, 230, 251 and 463 Vehicles Garage Door Opener Cannot Be Programmed and/or Range is Too Short
Apr 05, 2008	S-B-01.45/21	Models 164, 211, 251 with Engine 642, Model Years 2007-2008 Oil Leakage in Area of Oil Pan
Apr 04, 2008	S-B-83.00/116	All 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles AC Control Module / Control Functions
Apr 02, 2008	S-B-27.00/105	Model 164.122/822 Model 211.022 Model 251.122 Harsh Activation of Torque Converter Lockup Clutch
Apr 02, 2008	S-B-27.00/104	Model 164.122/822 Model 211.022 Model 251.122 Slow Acceleration with Gas Pedal Hesitation
Mar 26, 2008	T-B-88.70/72b	Revision: VIN Range Include and Remedy Amended All Model 164 Vehicles, Up to VIN A359047, All Model 251 Vehicles, Up to VIN A074553 Equipped with Electric Folding Mirrors (SA code 500) Exterior Mirror Does Not Fold Completely In or Out
Mar 26, 2008	S-B-83.00/115	All Model 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230 and 251 Vehicles Unpleasant Odor from Air Conditioning Vents
Mar 26, 2008	S-B-82.70/619	Model 164.122/172/175/177/186, Model 203.052/054/076/087/092 Model 209.356/372/377/456/472/477, Model 211.022/056/072/077/087/090/277/287 Model 219.372/377, Model 230.471/472/477/479, Model 251.122/156/165/175/177 As of Model Year 2007, Equipped with Cellular Telephone System Driver Cannot Hear the Calling Party During a Hands-Free Call or Calling Party Volume Very Low
Mar 26, 2008	T-B-03.30/09a	Revision: Combination of DTBs, Model 164.186/871, Model 251.165 Equipped with M272 Engine Up to Serial No. 2729..30 468993 or M273 Engine Up to Serial No. 2739..30 088611 Check Engine Light On / Fault Codes FC1200 / FC1208 Stored in ME-SFI Control Unit
Mar 25, 2008	T-B-91.10/132a	Revision: Technical Content Revised Model 164.122/175/177/186/822/871, Up to VIN A258966 Model 251.122/165/175/177, Up to VIN A058266
Mar 24, 2008	S-B-91.18/151	Head Restraint and/or Seat Adjustment Nonfunctional and/or SRS Illuminated All Passenger and Light Truck Models, Dirty Seats

Mar 24, 2008	T-B-91.12/149	All Model 251 Vehicles, Cracking Noises from Second Row Seat Backrest Model 164.122/172/175/177/186/822/871/886
Mar 24, 2008	T-B-68.10/73	Except Vehicles Equipped with the Off-Road Package (SA code 430) Storage Compartment in Center Console Does Not Open / Sticks
Mar 14, 2008	T-B-46.00/50a	Revision: Combination of DTBs, All Model 163/164 and 251 Vehicles Conditions Concerning the Steering System
Mar 12, 2008	S-B-82.60/617	MODELS 164, 171, 203, 204, 209, 211, 215, 216, 219, 220, 221, 230, 251, 463 Satellite Radio General Activation Information
Mar 11, 2008	T-B-15.40/61a	Revision: Combination of DTBs, Model 164.122/186/822/871 Model 251.165 Returning Alternators and Regulators Equipped with BSS or LIN Communication
Mar 07, 2008	C1A 080301	Customer 1 Action: Models 164, 164.8, 171, 204, 209, 211, 216, 219, 221, 230, 251, 463 Model Year 2008 Digital Tele Aid Reprogramming
Mar 03, 2008	S-B-46.25/37a	Models 129, 140, 163, 164, 170, 171, 199, 202, 203, 204, 208, 209, 210, 211, 215, 216, 219, 220, 221, 230, 251, 463, Processing of Steering System Complaints
Feb 22, 2008	T-B-97.00/04	All Model 164 / 251 Vehicles, Replacement Parts with Seam Seal
Feb 12, 2008	S-B-46.30/21a	Model 163.154/157/172/174/175 164.172/175/186/871/886 251.156/165/175 + others Noise from the Area of the Steering System / Power Steering Pump
Feb 08, 2008	S-B-40.10/18a	All Models, Chrome Plating of Mercedes-Benz Light Alloy Wheels
Feb 01, 2008	2008010005	Recall: Models 164, 164.8, 211, 251 with Diesel Engine OM 642 Model Years 2006 - 2008 Replace Crankshaft Position Sensor
Feb 01, 2008	T-B-82.64/608	Model 164.122/172/175/177/186/822/871/886, as of MY 2006 Model 251.122/156/165/175/177, as of MY 2006 Equipped with Option Code 819 CD Changer Cannot Be Operated / CDs Not Drawn In or Ejected, Jumps, Skips or Sets Over Temperature Fault Codes
Jan 15, 2008	T-B-82.85/593d	Revision: Document Discontinued Model 164 Model 251, As of MY 07 Equipped with Navigation System Code 530 Navigation Database Update At Pre-Delivery Inspection
Jan 15, 2008	T-B-32.22/50a	Revision: Reference to Figure Revised Model 164 with code 489 (Airmatic suspension) Model 251 Airmatic Inoperative / "Visit Workshop" Displayed in Instrument Cluster
Jan 11, 2008	T-B-82.62/594a	Revision: New Cause and Remedy Added Model 164 Model 251 Model Year 2006 with Option Code 810 (Sound Amplifier) Audio Not Available During Start Up or Sound Amplifier Not Visible During Quick Test
Jan 09, 2008	T-B-80.57/47	All Model 164 and 251 Vehicles, Diagnosis and Replacement of DAS3 Components
Jan 09, 2008	T-B-14.30/24	Model 164.177 Model 251.177 Check Engine Lamp Illuminated / DTC Codes 0817 or 0821
Jan 07, 2008	T-B-82.30/583a	Model 164.175/186 Model 251.165/175 Model Year 2006 (SA code 806) Rear Window Wiper Fails to Function or Stops Intermittently
Jan 03, 2008	T-B-42.45/87	All Model 164 Vehicles Equipped with Sales Code 477 - Tire Loss Warning System (indirect ESP based) with Run Flat Tires, Model Year 2005 to 2007 "Tire Pressure Monitoring Inactive" Displayed in Instrument Cluster
Jan 03, 2008	T-B-14.30/20b	Model 164.871, Up to and Including VIN A150065 Check Engine Light On / Fault Codes 0810, 0814 (P0410) Stored in Engine ECU
2007		
Dec 26, 2007	T-B-83.00/93	Model 164.122/175/177/186/822/871, Reduced Climate System Performance
Nov 30, 2007	2007110002	Service Campaign Models 164, 164.8, 251 Model Years 2007 - 2008 Install Rear Entertainment Software
Nov 12, 2007	T-B-54.15/190	Model 164.122/172/175/177/186 Rear SAM Enhanced Diagnostic Assistance Center
Nov 09, 2007	T-B-72.12/87	Model 164.122/172/175/177/186/822/871/886, Up to VIN A258996 Model 251.122/156/165/175/177, Up to VIN A058266 Knocking Noise in Rear Door When Operating Power Window
Nov 02, 2007	2007100003	Service campaign. Models 211, 164, 164.8, 251, with OM 642 MY 2006 - 2007 Update Engine Control Module Software, about 200 affected
Oct 26, 2007	T-B-42.45/82	Model 164.175, Up to VIN A038732 ESP Visit Workshop Displayed in Instrument Cluster
Oct 17, 2007	T-B-91.60/93g	Model 164.122/175/177/186/822/871/886 Model 251.122/165/175/177 Restraints - SRS Lamp ON and/or DTC's 9200 and/or 9210 Set
Oct 05, 2007	T-B-82.60/596	Model 164 VIN Range A249659 to A315197 Model 251 VIN Range A057022 to A064910 Model Year 2008 Equipped with Option Code 864 (Rear Seat Entertainment) Rear Seat Entertainment Systems Displays Do Not Power On, No Picture or Completely Inop
Oct 01, 2007	2007080003	Recall: Model X164 (GL320 CDI) Model Year 2007 Replace Charge Air Hoses (OM642 Engine)
Sep 28, 2007	T-B-27.60/99a	Model 164.122/822, Model 251.122 (turbodiesels) Automatic Transmission Occasionally Shifts Too Late or Does Not Shift Up
Sep 28, 2007	T-B-07.61/79	Model 164.172/186/871/886 Model 251.156/165 Check Engine Light Illuminated / Fault Code P0217 Stored in Engine Control Unit
Sep 28, 2007	2007090001	Service Campaign: Models 164, 164.8, 251 (with mechanical mirrors) Model Years 2006-2007 Lubricate Folding Mechanism of Right and Left Outside Mirrors with A000 989 3860
Sep 24, 2007	T-B-83.00/98b	All Light Truck Models, Air Conditioning Not Cooling, Leak Test Using Fluorescent Dye
Sep 18, 2007	2007070002	Service Campaign: Model 164 Model Year 2006 Rework Stainless Steel Under-Ride Guards on Front and Rear Bumpers
Sep 10, 2007	T-B-47.20/52	MY-All Models 164, 251 Procedure for Replacing Fuel Pump and Fuel Filter Modules
Sep 10, 2007	T-B-28.60/08	Model 164.871, Equipped with ORP Code 430 to June 2006 Production, VIN A152125 Message Low Range Service Required with DTC 2950 Stored in Transfer Case Control Module
Sep 04, 2007	T-B-07.16/77	Model 164.122/822 Model 251.122 Leaking High Pressure Fuel Pump / Possible Fuel Loss / Odor
Aug 28, 2007	T-B-83.00/106	Model 164 Model 251 AC Compressor Not Operating at Cold Temperatures
Aug 21, 2007	S-B-27.00/101	MY All Models All With Transmissions 722.4/5/6/9 Do Not Operate the Accelerator Pedal and Brake Pedal Simultaneously
Aug 20, 2007	T-B-14.20/22	Model 164.122/822 Model 251.122 Engine Changes to Limp-Home Mode and/or Has Insufficient Power
Aug 17, 2007	S-B-68.00/54b	Models 164/ 203/ 209/ 211/ 216/ 219/ 221/ 251 Model Year-All One-Time Use of Expansion Rivet with Sealing Function Reusing expansion rivets may cause water leakage
Aug 15, 2007	T-B-99.00/326	Technical Literature Announcement, Electrical TroubleShooting Manual, Starting Model Year 2006, Model 251, Volume 1 & 2, Supplement 1 released
Aug 14, 2007	S-B-07.16/68	MY-ALL, Models 164, 164X, 211, 251 with Engines 642, 648, Notes On Diesel Engines
Aug 9, 2007	T-B-82.15/691	All Model 164/ 251 Vehicles, As of Model Year 08 (SA code 808) and Headlamp Washing System (SA code 600): Headlamp Washer Switch
Aug 7, 2007	T-B-83.40/77a	Climate System Temperature Too Cold or Too Warm Compared to Panel Setting
Aug 1, 2007	T-B-97.00/02	MY-All Models 163, 164, 251 Introduction of Replacement Parts with Seam Sealant
Aug 1, 2007	S-B-91.00/37	Model Year - All Models All Repairs for Noise Complaints Regarding Seats
Jul 25, 2007	T-B-47.25/45	Model 164.177, Up to VIN A185373 Engine Ticking Noise at Idle
Jul 19, 2007	T-B-07.61/75	Equipped with Engine M112 / M113 / M272 or M273 Diagnosis in DAS for Purge System Codes / Check Engine Light Illuminated
Jun 27, 2007	T-B-91.60/135	Model 164.122/175/177/186 SRS Initial Startup Faults
Jun 26, 2007	S-B-33.20/27	MY-All Models 164, 216, 221, 251 and Model 211 as of January 2007 Disassembling of Ball Joints with Race
Jun 21, 2007	S-B-99.00/222L	<u>Star Service Manual on DVD for R-Class (W251) released: part number P-2700-251-07</u> includes OM642 diesel engine info
Jun 21, 2007	T-B-46.20/58	All 163, 164 and 251 Models Equipped with Rack-and-Pinion Steering

Jun 18, 2007	T-B-82.35/588	Model 164.122/175/177/186/822/871, Model 251.122/165/175/177 Washer Fluid Level Sensor Not Functioning Correctly
Jun 14, 2007	T-B-83.00/104	All Model 164 and 251 Vehicles, Model Year 2006 through 2007 Vehicle Heating, Ventilation, Air Conditioning (HVAC) Manual available for troubleshooting
Jun 12, 2007	T-B-82.60/582	Model 164.122/175/177/186/822/871, as of Model Year 2006 Up To VIN A213513 Model 251.122/165/175/177, as of Model Year 2006 Up To VIN A051176 Equipped with Option Code 864 (Rear Seat Entertainment System)
Jun 8, 2007	2007020004	Service Campaign: Models 164, 209, 211, 219, 251 AMG Model Year 2007 Install Support for Intake Manifold Switchover Flap (M156 Engine)
Jun 1, 2007	2007040007	Service Campaign: Model 164.177 AMG, Model Year 2007 Replace Left Engine Oil Line (M156 Engine)
May 22, 2007	T-B-91.60/134	Model 164.122/175/177/186/822/871 Model 251.122/165/175/177 Model Year 2007 SRS High Resistance for Side Airbag / DTC 9290 and/or 92A0: replace squid connector
May 22, 2007	T-B-54.18/185	All Model 164 and 251 Vehicles, Work on Electrical Connectors: Disconnect battery only when needed
May 22, 2007	S-B-15.40/58a	Test and Inspection of Charging System Regulator When alternator fails test/replace failed regulator instead of replacing alternator
May 21, 2007	T-B-88.70/49a	All Light Truck Models, Moisture in Additional Turn Signal Lamp(s) in Rearview Mirrors
May 14, 2007	T-B-72.20/43d	Model 164.122/175/177/186 Model 251.122/165/175/177 Model Year 2006 Power Closing Assist on the Tailgate Intermittently Nonfunctional
May 8, 2007	T-B-83.30/91b	All Model 164 and 251 Vehicles, Air Conditioning Musty/Moldy Odor Complaints
May 7, 2007	T-B-68.10/67	Model 164 Noises at the Instrument Panel Describes how to remove 4 different noises if present on instrument panel
Apr 27, 2007	P-B-82.60/426b	All Model 164 / 251 and 463 Model Year 2004 to 2007 Diagnostic Enhancement: Satellite Radio (SDARS) Enhanced Diagnostic Assistance
Apr 27, 2007	2007040003	Service campaign: Models 164, 211, 251, X164, Model Year 2007 Replace Engine Oil Filler Neck Seal (OM642 Engine)
Apr 18, 2007	T-B-40.15/56b	Revised Instruction for Siemens Systems All Light Truck Models with Tire Pressure Control, Tire Pressure Control (TPC) Repairs
Apr 17, 2007	T-B-88.20/63	Corrosion of Mercedes Star in Distronic Plate
Apr 10, 2007	T-B-41.10/03a	Up to June 30, 2005 Production Date, VIN Range A000826 to A026114 Vibration at Front Driveshaft While Driving at Highway Speeds
Mar 30, 2007	2007020007	Campaign: Model X164 (GL) Model Year 2007 MB determined affected vehicles had no roof crossbars
Mar 29, 2007	T-B-27.00/96	All Light Truck Vehicles Equipped with Transmission 722.9 Trans. in Limp-Home Mode or Harsh Engagement After Programming / SCN Coding Revision: Applicable Models Updated
Mar 28, 2007	T-B-27.60/65a	All Light Truck Models Equipped with 7G-Tronic (722.9) Transmission Learning in Selection Range Sensor Not Possible After EHS Replacement
Mar 28, 2007	T-B-27.35/97	All Light Truck Models Equipped with 7G-Tronic (722.9) Transmission No Transfer of Power from Transmission
Mar 9, 2007	T-B-31.19/07d	Installing Electric Trailer Brake Controller
Mar 5, 2007	T-B-83.30/91a	All 164/251, Air Conditioning Musty/Moldy Odor Complaints: Use MB Contra Sept cleaner
Mar 2, 2007	2007010004	Campaign: X164, Check Intake Manifold and Replace if Necessary, update M273 software
Mar 1, 2007	T-B-82.85/545	Model 164/251 as of MY 06 Equipped with iPod Interface Kit
Feb 26, 2007	T-B-18.40/30b	Warranty info updated: Leakage Between Oil Level Sensor and Oil Pan
Feb 20, 2007	2007010001	Campaign: MY2007 AMG: Replace Poly V-Belt and Tensioner (M156 Engine)
Feb 13, 2007	T-B-30.16/64a	Revision: Testing of Throttle Valve Sensor, M113 ME2.8, M272/273 engines
Feb 10, 2007	T-I-82.70/571	Preliminary draft: Voice control installation MY2007 Model GL450 (up to VIN A150126)
Feb 9, 2007	T-B-83.00/89	Climate System Temperature Setting Not Possible/LED Indicator wont Change: update SW
Feb 9, 2007	T-B-27.60/93	722.9 (7G-Tronic) Adaptation Values of the 6-5 Downshift Close to the Negative Limit
Feb 9, 2007	2007010008	Campaign - MY2007 Check/update 722.9 transmission software Update M273 SW if required
Feb 6, 2007	T-B-07.00/53c	Engines M113 (ME2.8) M156, M272, M273 Control Unit: all returned units will be tested
Feb 5, 2007	T-B-40.15/57	Display "Tire Pressure Monitor Unavailable" and Fault Lamp Flashes: fuel pump interferes
Feb 5, 2007	T-B-46.10/39a	Chrome Plating Peeling on Decorative Caps on the Steering Wheel Spokes: replace caps
Feb 5, 2007	T-B-98.10/18	Paint Blistering / Loss of Adhesion on Liftgate: strip and refinish
Feb 2, 2007	T-B-72.00/76	Model 251 Up to VIN A051018 Interior Door Handle Noises: apply spray 000 989 3560
Feb 1, 2007	T-B-83.00/81	Malfunctions of Various Control Units and/or On-Board Power Supply Problems: moisture
Feb 1, 2007	T-B-54.65/182	Parktronic Triggers Without Obvious Cause at Front Bumper Due to License Plate Width
Jan 31, 2007	T-B-82.00/261b	MY2000 through current model year, light trucks: CDs and DVDs May Not Be Ejected
Jan 12, 2007	2006120008A	<u>Recall - Accelerator Pedal Mounting</u>
Jan 10, 2007	T-72.20/43C	Body - Power Tailgate Closing Assist Intermittently Inop
Jan 10, 2007	T-18.00/33A	Engine - Oil Level is Too Low
Jan 4, 2007	S-B-99.00/222J	<u>Availability of Star Service Manual Libraries on CD/DVD-ROMs: T-2700-164-06 does not include OM642 diesel engine</u>
Jan 4, 2007	T-05.20/21	Engine - Sporadic Noise On Warm Start Up

2006

Dec 12, 2006	T-72.12/69	Body - Stone Chips in Area of Rear Doors
Dec 1, 2006	2006110005B	Campaign - Install Software for Navigation System
Dec 1, 2006	2006120004	Campaign - Replace Trailer Hitch
Nov 29, 2006	T-88.70/56	Body - Creaking Noise When Mirrors Folded Out
Nov 29, 2006	T-88.79/57	Body - Exterior Mirror Cannot Be Adjusted
Nov 29, 2006	P-82.85/532A	Diagnostic Enhancement - MCSII EDAC
Nov 28, 2006	T-15.40/61	Charging System - Returning Alternators & Regulators
Nov 27, 2006	T-32.22/45	Suspension - Cracking, Knocking or Thumping Noises
Nov 27, 2006	T-54.30/180	Instruments - After SCN Coding IC Shows No Menus
Nov 27, 2006	T-27.60/89	Transmission - 722.9 - Fault Codes 2502, 2505, P0894 or P2711
Nov 27, 2006	T-B-27.60/62e	Equipped with 7G-Tronic Transmission (NAG2) Rough Shift Quality: Readapt, SW upgrade, check circlip
Nov 22, 2006	2006110005A	Campaign - Navigation DVD Update
Nov 7, 2006	T-27.60/68E	Auto Trans - Uncomfortable 2-1 Coastdown Downshift
Nov 7, 2006	T-32.22/44	Traction Control - Acceleration Sensor Elimination
Nov 7, 2006	T-72.10/72	Body - Wind Noise From Upper Rear of Front Door
Nov 6, 2006	T-09.20/27	Engine - Shakes at Idle and or MIL ON and or Codes 0745 and or 0749
Oct 31, 2006	T-46.10/48	Steering Wheel - Multi-Function Buttons Inoperative
Oct 27, 2006	T-27.60/68D	Auto Trans - Uncomfortable 2-1 Downshift When Coasting and or Braking
Oct 27, 2006	2006060005A	Campaign - Exhaust System Modification
Oct 26, 2006	S-27.56/83	Transmission - Filter Part Number and or Replacement Information; pan magnets
Oct 24, 2006	S-27.19/82	Auto Trans - Electrohydraulic Control Unit Part Numbers
Oct 19, 2006	2006100003	Campaign - Starter Wiring Harness routing
Oct 12, 2006	T-91.40/129	Restraints - 'PRE-SAFE Not Available' Message Displayed
Oct 2, 2006	T-91.60/122	Restraints - SRS Lamp ON and or Codes 90C6 and or 90D6 and or 90E6 & 90F6
Oct 2, 2006	T-83.10/80A	Air Conditioning - Water Leaks Into The Interior
Sep 27, 2006	T-82.60/456B	Entertainment System - iPod(R) Interface Errors

Sep 27, 2006	T-47.00/41	Instruments - Fuel Gauge Drops To 'EMPTY'
Sep 13, 2006	S-68.00/54	Restraints - Poor Rear Seat Belt Fit and or Head Restraint Inop
Sep 1, 2006	2006090001	Campaign - Sluggish Auto Trans Shifting
Aug 30, 2006	T-27.60/81	Engine, Auto Trans Controls - DTC 061B After Reprogramming
Aug 29, 2006	T-67.39/21	Body - Rear Window Express Feature Inoperative
Aug 29, 2006	T-91.30/103A	Interior - Front Seat Heaters Inoperative
Aug 15, 2006	T-27.60/55B	Transmission - Noises When Using 'Direct Select' Mode (Normal)
Aug 1, 2006	2006060005	Campaign - Exhaust System Shim Plate Installation
Aug 1, 2006	2006080003	Campaign - COMAND(R) and or Navigation Software Update
Aug 1, 2006	S-67.00/20	Body - Laminated Glass Chip and or Crack Repair Information
Jul 21, 2006	T-46.00/45	Steering - Power Steering Fluid Requirements
Jul 20, 2006	2006040002	<u>Recall - Model 251, MY2006 Repair or Replace Starter Wiring Harness</u>
Jul 19, 2006	T-82.60/508	Entertainment System - No Audio From iPod(R)
Jul 14, 2006	T-27.60/62D	Transmission - Harsh 1-2, 3-2 and 2-1 Shifts
Jul 13, 2006	2006060002	Campaign: Model 164 MY2006 Inspect Air Suspension Compressor and Replace if Necessary (AMK air compressor)
Jun 30, 2006	T-46.10/39	Interior - Chrome Peeling Off Steering Wheel Spokes
Jun 15, 2006	T-88.20/47	Parktronic(R) System - Activates By Itself
Jun 14, 2006	T-72.10/65	Interior - Door Trim Panel Creaking Noise
Jun 13, 2006	T-88.70/49	Lighting - Moisture In Turn Signals In The Mirrors
Jun 8, 2006	T-32.20/39	Suspension - Rear End Creaking and or Grunting Noise On Bumps
Jun 6, 2006	T-88-80-51	Body - Windshield Water Deflector Protrudes Upwards
Jun 1, 2006	2006040007	Campaign - Spare Tire Inspection and or Replacement
Jun 1, 2006	T-63.50/09	Body - Fuel Filler Flap Is Loose
May 26, 2006	T-82.85/506	Model 164, Model Year 2006 Model 251, Model Year 2006 Head Unit Not Turning ON or Intermittently Locking Up Message "TeleAid Visit Workshop" Displayed In the Instrument Cluster MODEL 163.154/157/172/175 (starting with MY2001) MODEL 164.175 MODEL 251.175 MODEL 463.249 Troubleshooting Fault Codes Related to: - Adaptation Limits of Lambda Control - Mass Air Flow Sensors / Intake Air Temperature Sensor
Apr 26, 2006	T-00.00/81C	Engine - Increased Oil Consumption
Apr 20, 2006	T-54.30/136D	Instruments - SCN Coding for Components R & R
Apr 11, 2006	T-83.40/77	Air Conditioning - Actual Temperature Differs From Setting
Apr 11, 2006	T-05.20/17A	Engine Controls - MIL ON and or DTC P2034 Set
Apr 10, 2006	T-27.60/68C	Auto Trans - Harsh 2-1 Downshift When Braking or Coasting
Apr 07, 2006	T-I-82.70/435C	Installation Bulletin Model 164.175/186 (Models with Tele Aid*) Model Year 2006 Cellular Telephone Installation (5 MB)
Apr 3, 2006	T-82.95/501	Cell Phone - TeleAid(R) Calls Will Not Connect
Apr 1, 2006	2006040003	<u>Recall - Model 251 Model Year 2006 2nd Row Seat Inspection and or Replacement</u>
Apr 1, 2006	T-82.60/440A	Entertainment System - Rear Seat System Installation
Apr 1, 2006	T-82.70/435C	Cellular Phone - Installation Instructions
Mar 23, 2006	T-82.70/493	Audio System -Poor Audio Quality When Using Cell Phone
Mar 20, 2006	T-82.95/495	Cell Phone - Digital TeleAid(R) Calls Won't Connect
Mar 15, 2006	T-32.25/20A	Suspension - Strut and or Shock Replacement Guidelines
Mar 3, 2006	T-88.30/43	Body - Rear Engine Compartment Cover Broken
Mar 3, 2006	T-42.45/63A	Brakes - Multiple Warnings Displayed on Instrument Panel
Mar 1, 2006	2006010005	Campaign - Strut Tower Reinforcement
Feb 28, 2006	T-91.30/103	Interior, Air Conditioning - Driver and or Passenger Seat Heaters Inop.
Feb 24, 2006	T-72.20/43B	Body - Power Tailgate Closer Intermittently Inoperative
Feb 1, 2006	2006010002	Campaign - Spare Wheel Bolt Package Inspection
Jan 20, 2006	T-27.60/68	Auto Trans Controls - Uncomfortable and or Harsh 2-1 Coast Downshift
Jan 10, 2006	T-82.30/453A	Wipers - Noisy and or Chattering After Wiper Blade Replacement
Jan 2, 2006	T-61.30/04	Body and or Suspension - Rubbing Noise From Rear

2005

Dec 22, 2005	T-I-82.70/454A	Installation Bulletin Model 251.165/175 (Models with Tele Aid*), Model Year 2006 Cellular Telephone Installation (6MB)
Dec 21, 2005	T-94.10/04	Body and or Restraints - Noise From C-Pillar Area
Dec 19, 2005	T-27.60/67	Engine Controls - Incorrect Software Loaded
Dec 13, 2005	T-27.60/65	Auto Trans Controls - No Range Sensor Learning After EHS R & R
Dec 12, 2005	T-91.60/93	Air Bag System - SRS Lamp ON and or DTC's 9200 and or 9210 Set
Dec 1, 2005	T-82.95/480	Cell Phone - Can't Connect Call and or FC D662 in TeleAid Unit
Nov 29, 2005	T-07.00/56	Engine Controls - Engine Hesitation and or Stalling on Start-Up
Nov 21, 2005	T-54.30/151	Instruments - Entering Total Mileage Into Cluster
Nov 21, 2005	T-77.20/41	Body - Sunroof Wind Deflector Glass Panel Interference
Nov 17, 2005	T-41.10/03	Drivetrain - Highway Speed Front Driveshaft Vibration
Nov 17, 2005	T-82.60/474	Audio System - ESN Number Missing From Display
Nov 7, 2005	T-72.20/53	Body - Tailgate Cannot Be Opened
Nov 7, 2005	T-82.62/470	Audio System - No Reception in AM-FM and or Weather Bands
Nov 5, 2005	T-54.21/154A	Antitheft System - ATA Fault Code 90C7 in Rear SAM
Aug 1, 2005	T-82.85/441C	Navigation System - DVD Navigation Installation
May 1, 2005	2005050004	<u>Recall - Power Steering Hose Clamp Replacement</u>
Apr 1, 2005	T-82.60/440	Entertainment System - Rear Seat Entertainment System
Apr 1, 2005	T-82.85/441B	Navigation System - DVD System Installation and or Setup
Mar 30, 2005	T-82.60/442	Instruments - Phone Menu Messages Displayed
Mar 18, 2005	AP00.20-P-0	<u>Reset Service Indicator Model 251 (also Model 164)</u>
Mar 01, 2005	T-82.60/438	Entertainment Systems - iPod(R) Integration Kit
Feb 28, 2005	S-B-99.00/300	INTRODUCTION INTO SERVICE MANUAL (PRELIMINARY) STARTING MODEL YEAR 2006 MODEL 164

Mercedes-Benz W164, W251 and X164 (new ML, R, GL) DTBs

Wolfgang's MB Page