

VCDS  
Windows Based VAG/VAS Emulator  
VCDS Version: Release 12.12.0(x64) Data version: 20130910  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000 000000

Self-Diagnosis Log  
Friday,27,July,2018,21:40:59:62939

VIN: TMBBC65JX83070670 License Plate:  
Mileage: Repair Order:

Chassis Type: 5J (5J - Skoda Fabia (2007 > 2010))  
Scan: 01 02 03 08 09 15 16 17 19 25 37 44 46 55 56 76 77

VIN: TMBBC65JX83070670

-----  
Address 01: Engine Labels:  
VCID: 55A167DFACF48DB6975

-----  
Address 03: ABS Brakes Labels: 6R0-907-37x-ESP80.lbl  
Part No SW: 6Q0 907 379 AP HW: 6Q0 907 379 AP  
Component: ESP 8.0 front H03 0001  
Revision: 00000000 Serial number: 0000000000000000  
Coding: 0000311  
Shop #: WSC 13765 790 00000  
VCID: 8B15C1A7E9B00B46711-5072

No fault code found.

-----  
Address 08: Auto HVAC Labels: 6Q0-820-045.lbl  
Part No: 5J0 820 045  
Component: Klimaanlage X0850  
VCID: E2CBCC036EBAEA0E627-5072

No fault code found.

-----  
Address 09: Cent. Elect. Labels: 6Qx-937-049-C.lbl  
Part No: 6Q1 937 049 F  
Component: 0000 BN-SG. 2S36  
Coding: 25742  
Shop #: WSC 13765  
VCID: 3E73D8733A826EEEA6F-5072

2 Faults Found:  
01309 - Power Steering Control Module (J500)  
49-10 - No Communications - Intermittent  
01598 - Drive Battery Voltage  
07-10 - Signal too Low - Intermittent

VCDS  
Self-Diagnosis Log  
Friday,27,July,2018,21:40:59:62939  
Page 2

VIN: TMBBC65JX83070670 License Plate:

Address 15: Airbags Labels: 6Q0-909-605-VW5.lbl  
Part No: 1C0 909 605 F  
Component: QA AIRBAG VW61 Q5Q6 0004  
Coding: 20801  
Shop #: WSC 13765  
VCID: 275D1D17C518CF26F59-5000

1 Fault Found:  
00532 - Supply Voltage B+  
07-10 - Signal too Low - Intermittent

---

Address 17: Instruments Labels: 5J0-920-xxx-17.clb  
Part No: 5J0 920 810 B  
Component: KOMBIINSTR. V2823466  
Coding: 19113  
Shop #: WSC 13765  
VCID: 2541171FBF14DD36C75-5000

No Faults Found  
or DTCs not supported by controller  
or a communication error occurred

---

Address 19: CAN Gateway Labels: 6N0-909-901-19.lbl  
Part No: 6N0 909 901  
Component: 000E GATEWAY CAN 2S36  
Coding: 00014  
Shop #: WSC 13765  
VCID: F0EFB64BB056489EE43-5072

1 Fault Found:  
01309 - Power Steering Control Module (J500)  
49-10 - No Communications - Intermittent

---

Address 25: Immobilizer Labels: 5J0-920-xxx-25.clb  
Part No: 5J0 920 810 B  
Component: IMMOBILIZER V2823466  
Coding: 19113  
Shop #: WSC 13765  
VCID: 2541171FBF14DD36C75-50E6  
TMBBC65JX83070670 SKZ7Z0G4492971

No fault code found.

---

VCDS  
Self-Diagnosis Log  
Friday,27,July,2018,21:40:59:62939  
Page 3

VIN: TMBBC65JX83070670 License Plate:

Address 44: Steering Assist Labels: 6Q0-423-156.clb  
Part No: 6Q0 423 156 AB  
Component: LenkhilfeTRW V270  
Coding: 10140  
Shop #: WSC 13765  
VCID: 6FED35372D68D7667D9-5072

1 Fault Found:  
00566 - Steering Assistance Operation  
27-10 - Implausible Signal - Intermittent

-----  
Address 46: Central Conv. Labels: 6Q0-959-433.lbl  
Part No: 5J0 959 433 A  
Component: 03 Komfortgerát 0001  
Coding: 00019  
Shop #: WSC 13765  
VCID: 3169F34FFBDC81962BD-4A3A

No fault code found.

-----  
Address 56: Radio Labels: 1K0-035-1xx-56.lbl  
Part No SW: 5J0 035 161 HW: 5J0 035 161  
Component: Radio FO3 010 0029  
Revision: 00010000 Serial number: SKZ7Z3G0089062  
Coding: 0000400  
Shop #: WSC 13765 790 00000  
VCID: DFCDC5F70DC8C7E64D9-5072

No fault code found.

End -----