

## Phone adapter for mobile phone preparation with Bluetooth®

When choosing a phone adapter, please note which generation of the universal mobile phone preparation your car has. You can determine the generation of your mobile phone preparation with reference to the pictures below.



### Generation I

to be recognized by the spiral cable

### Generation II

to be recognized by the gold contacts on the base plate

### Generation III

to be recognized by the semi-round enhancements on the base plate, left and right of the gold contacts

With generation I of the mobile phone preparation, the electrical connection between phone adapter and hands-free kit is established via the cable coil on the adapter.

With generation II and III of the mobile phone preparation, there is a gold-plated strip on the adapter base.

You can see below for which mobile phones an adapter is available.

### Phone adapter for generation I (with cable coil)

Page 2

### Phone adapter for generation II (without cable coil)

Page 3

In vehicles with generation II of the Audi mobile phone preparation (Bluetooth®), it is possible to connect the phone via Bluetooth.

In cars with generation III AUDI mobile phone preparations, mobile phones are exclusively connected through Bluetooth.

More information is available at [www.audi.de/telefon](http://www.audi.de/telefon).

### Sart Dates

#### Generation I:

A2 approx. ->06/2003  
A3 approx. ->MY 2003  
A4 & Cabrio with Phone adapter fitted in Armrest ->CW 21/2004 at the dashboard ->CW 35/2003  
A6 (4B) ->MY 2005  
A8 approx. ->MY 2003  
TT approx. ->06/2003

#### Generation II:

A2 approx. 07/2003->2005  
A3 approx. MY 2004->  
A4 & Cabrio with Phone adapter at the dashboard CW 36/2003->CW 21/2004  
A4 MY 2005->2008  
Cabrio MY 2005->  
A4 (8K) approx. MY 2008->  
A5 without Navigation MY 2008->  
A5 with MMI basic plus MY 2008->2009  
A5 with MMI DVD Navigation MY 2008->CW 44/2008  
A6 (4F) MY. 2005->approx. 08/2008  
A8 (4E) MY 2004->approx. 08/2008  
A8 (4E) without Navigation approx. 09/2008->  
Q5 without navigation system MY 2009->  
Q7 MY 2007->  
R8 MY 2007->  
TT approx. 07/2003 ->

#### Generation III:

A5 with MMI Navigation plus CW 45/2008->  
A6 approx. 09/2008 ->  
A8 with MMI Navigation plus approx. 09/2008 ->  
Q5 MY 2009 -> (with navigation system)

**Note: Not all mobile phones support the entire range of functions associated with the universal mobile phone preparation with Bluetooth®**

**Note: Playback of music titles stored on the mobile telephone is not possible via the universal mobile phone preparation**

## Determining the firmware version of your mobile phone\*

Should your mobile phone feature in the table below but, nevertheless, not function with the universal hands-free system, this could be due to the firmware on your phone. The firmware versions which you should use are listed in the tables. You can identify your mobile phone's software by pressing the following buttons on the handset:

### Motorola

Display software version Select: Menu – Settings – Phone settings  
– More information – SW version

### Nokia

Display software version \*#0000#

### BENQ Siemens

Display software version \*#06# and the left display key

### Sony Ericsson

Display software version (control sequence using cursor) right, \*, left, left, \*, left, \*, 2x Confirm

You can get a firmware update for your phone from the manufacturer or from your network provider.

If you have any further questions about universal mobile phone preparation or about mobile phone adapters, please contact your Audi dealer or visit [www.audi.com/contact](http://www.audi.com/contact).

## Generation I phone adapter

Phone type		Phone adapter part number	Phone adapter part number
BENQ Siemens	S25	8D0 051 435 L	
	C35i	8D0 051 435 Q	
	M35i	8D0 051 435 Q	
	S35i	8D0 051 435 Q	
	C55	8D0 051 435 AG	
	M55	8D0 051 435 AG	
	S55	8D0 051 435 AG	
	C65	8D0 051 435 BB	
	CX65	8D0 051 435 BC	
	M65	8D0 051 435 BC	
	S65	8D0 051 435 BD	
	SP65	8D0 051 435 BD	
	CX70	8D0 051 435 BC	
	C75	8D0 051 435 BN	
	CX75	8D0 051 435 BJ	
	M75	8D0 051 435 BK	
Motorola	V60 (i)	8D0 051 435 AD	
	V300	8D0 051 435 AT	
	V400	8D0 051 435 AT	
	V500	8D0 051 435 AT	
	V525	8D0 051 435 AT	
	E550	8D0 051 435 AT	
	V550	8D0 051 435 AT	
	V600	8D0 051 435 AT	
	V620	8D0 051 435 AT	
	V635	8D0 051 435 AT	
Nokia	3100	8D0 051 435 AN	V3.4
	5110	8D0 051 435 R	
	6020	8D0 051 435 BP	
	6021	8D0 051 435 BP	
	6100	8D0 051 435 AL	
	6110 <sup>2</sup>	8D0 051 435 R	
	6130	8D0 051 435 R	
	6150	8D0 051 435 R	
	6151	8D0 051 435 DC	
	6210	8D0 051 435 R	
	6220	8D0 051 435 AM	
	6230	8D0 051 435 AQ	
	6230i	8D0 051 435 AQ	
	6233	8D0 051 435 DA	
	6234	8D0 051 435 CP	
	6280	8D0 051 435 CR	
	6288	8D0 051 435 CR	
	6310 (i)	8D0 051 435 AE	
	6610	8D0 051 435 AK	
	6820	8D0 051 435 AR	
	7110	8D0 051 435 R	
	7210	8D0 051 435 AK	
	7250(i)	8D0 051 435 AK	
Sony Ericsson	R320s	8D0 051 435 N	
	R380s	8D0 051 435 S	
	R520m	8D0 051 435 S	
	T28s	8D0 051 435 AA	
	T29s	8D0 051 435 AA	
	T39m	8D0 051 435 AA	
	T610	8D0 051 435 AH	
	T630	8D0 051 435 AH	
	K700i	8D0 051 435 BE	
	<div>1 All details relate to the recommended mobile-phone firmware version and are subject to correction. Similar functionality is to be expected from newer versions of the same firmware. This cannot, however, be guaranteed. Should a phone with older firmware not function properly with the universal mobile phone preparation, a newer version of the software should normally offer a solution.</div> <div>2 Not including Nokia 6110 Navigator</div>		

## Generation II and III phone adapter

Phone type		Phone adapter part number	Access to numbers on SIM card	Access to numbers stored on phone <sup>1</sup>	usable with Generation		Recommended firmware version <sup>2/</sup> observations
					II	III	
Apple	iPhone <sup>9</sup>	8P0 051 435 GP <sup>3,5</sup>	No	Yes	Yes	Yes	1.1.2
BENQ Siemens	C45	8P0 051 435 AP <sup>3</sup>	Yes	Yes	Yes	No	
	ME45	8P0 051 435 AP <sup>3</sup>	Yes	Yes	Yes	No	
	S45 (i)	8P0 051 435 AP <sup>3</sup>	Yes	Yes	Yes	No	
	M50	8P0 051 435 AP <sup>3</sup>	Yes	Yes	Yes	No	
	MT50	8P0 051 435 AP <sup>3</sup>	Yes	Yes	Yes	No	
	S55	8P0 051 435 CJ <sup>3</sup>	Yes	Yes	Yes	No	16
	M55	8P0 051 435 CJ <sup>3</sup>	Yes	Yes	Yes	No	16
	C55	8P0 051 435 CJ <sup>3</sup>	Yes	Yes	Yes	No	16
	C65	8P0 051 435 AT	Yes	Yes	Yes	No	25
	CX65	8P0 051 435 EG <sup>3</sup>	Yes	Yes	Yes	No	16
	M65	8P0 051 435 EG <sup>3</sup>	Yes	Yes	Yes	No	16
	S65	8P0 051 435 ED	Yes	Yes	Yes	No	41
	SP65	8P0 051 435 ED	Yes	Yes	Yes	No	47
	S68	8P0 051 435 EH <sup>3</sup>	Yes	Yes	Yes	No	22
	CX70	8P0 051 435 EG <sup>3</sup>	Yes	Yes	Yes	No	36
	C75	8P0 051 435 FC <sup>3</sup>	Yes	Yes	Yes	No	22
	CX75	8P0 051 435 DJ <sup>3</sup>	Yes	Yes	Yes	No	05
	M75	8P0 051 435 DL <sup>3</sup>	Yes	Yes	Yes	No	05
	S75	8P0 051 435 FB <sup>3</sup>	Yes	Yes	Yes	No	36
Motorola	V300	8P0 051 435 DD	Yes	Yes	Yes	No	Triplets_G_OB.08.A5R_A
	V400	8P0 051 435 DD	Yes	Yes	Yes	No	Triplets-G-0B.08.AAR-A
	V500	8P0 051 435 DD	Yes	Yes	Yes	No	Triplets-G-0B.09.38R
	V525	8P0 051 435 DD	Yes	Yes	Yes	No	Triplets_G_OB.09.37R
	E550	8P0 051 435 DD	Yes	Yes	Yes	No	R376_G_OE.65.14R_A
	V550	8P0 051 435 DD	Yes	Yes	Yes	No	R376-G-0E.65.26R
	V600	8P0 051 435 DD	Yes	Yes	Yes	No	Triplets_G_OB.09.38R
	V620	8P0 051 435 DD	Yes	Yes	Yes	No	R_376_G_OE.65.25R
	V635	8P0 051 435 DD	Yes	Yes	Yes	No	R376_G_OE.65.14R_A
Nokia	3100	8P0 051 435 AH <sup>3</sup>	Yes	Yes	Yes	No	4.06
	3109 classic	8P0 051 435 HD <sup>3,5</sup>	Yes	Yes	Yes	Yes	5.30
	3110 classic	8P0 051 435 HD <sup>3,5</sup>	Yes	Yes	Yes	Yes	5.30
	3110 Evolve	8P0 051 435 HD <sup>3,5</sup>	Yes	Yes	Yes	Yes	5.50
	6020	8P0 051 435 GB <sup>3</sup>	Yes	Yes	Yes	No	3.52
	6021	8P0 051 435 GB <sup>3</sup>	Yes	Yes	Yes	No	3.83
	6021	8P0 051 435 HB <sup>3,5</sup>	Yes	Yes	No	Yes	3.83
	6100	8P0 051 435 CM <sup>3</sup>	Yes	Yes	Yes	No	5.16
	6151	8P0 051 435 GG <sup>3</sup>	Yes	Yes	Yes	No	3.56
	6210	8P0 051 435 BQ <sup>3,4</sup>	Yes	No	Yes	No	5.56
	6220	8P0 051 435 Q	Yes	Yes	Yes	No	4.08
	6230	8P0 051 435 GC <sup>3</sup>	Yes	Yes	Yes	No	4.28
	6230i	8P0 051 435 GC <sup>3</sup>	Yes	Yes	Yes	No	3.40
	6233	8P0 051 435 GL <sup>3</sup>	Yes	Yes	Yes	Yes	4.52
	6234	8P0 051 435 GF <sup>3</sup>	Yes	Yes	Yes	No	4.91
	6280	8P0.051.435.FS <sup>3</sup>	Yes	Yes	Yes	Yes	5.92
	6288	8P0.051.435.FS <sup>3</sup>	Yes	Yes	Yes	Yes	5.92
	6300	8P0 051 435 HA <sup>3,5</sup>	Yes	Yes	Yes	Yes	5.00
	6310	8P0 051 435 BQ <sup>3</sup>	Yes	Yes <sup>6</sup>	Yes	No	5.01
	6310i	8P0 051 435 BQ <sup>3</sup>	Yes	Yes <sup>9</sup>	Yes	No	7.00
	6600	8P0 051 435 AG <sup>3,5</sup>	No	No	Yes	No	5.53
	6610	8P0 051 435 CK <sup>3</sup>	Yes	Yes	Yes	No	5.52
	6820	8P0 051 435 AD <sup>3</sup>	Yes	Yes	Yes	No	3.70
	7210	8P0 051 435 CK <sup>3</sup>	Yes	Yes	Yes	No	5.52
	7250 (i)	8P0 051 435 CK <sup>3</sup>	Yes	Yes	Yes	No	3.22
	E50	8P0 051 435 FF <sup>3,5</sup>	No	No	Yes	Yes	07.13.00
	E60	8P0 051 435 GD <sup>3,5</sup>	No	No	Yes	Yes	1.0610.02.15
Blackberry	8100	8P0 051 435 GH <sup>3,5</sup>	No	Yes	Yes	Yes	4.2.0.51
	8110	8P0 051 435 GH <sup>3,5</sup>	No	Yes	Yes	Yes	v4.3.0.93
	8120	8P0 051 435 GH <sup>3,5</sup>	No	Yes	Yes	Yes	v4.6.0.165
Sony Ericsson	T610	8P0 051 435 CL <sup>3</sup>	Yes	Yes	Yes	No	R3A
	T630	8P0 051 435 CL <sup>3</sup>	Yes	Yes	Yes	No	R4E und R6C
	K510i	8P0 051 435 FK <sup>3,5</sup>	Yes	Yes	Yes	Yes	R4CH003
	K610i	8P0 051 435 FJ <sup>3,5</sup>	Yes	Yes	Yes	Yes	R1ED001
	K750i	8P0 051 435 EN <sup>3,8</sup>	Yes	Yes	Yes	No	R1AA008
	K800i	8P0 051 435 GM <sup>3,5</sup>	Yes	Yes	Yes	Yes	R1ED001
	K810i	8P0 051 435 GM <sup>3,5</sup>	Yes	Yes	Yes	Yes	R1KG001
	W700i	8P0 051 435 EN <sup>3,8</sup>	Yes	Yes	Yes	No	R4CE012
	W800i	8P0 051 435 EN <sup>3,8</sup>	Yes	Yes	Yes	No	R1DE001
	W810i	8P0 051 435 EN <sup>3,8</sup>	Yes	Yes	Yes	No	R1DE001

1 This function is available only on vehicles manufactured in the production month 11/05 and after. Your Audi dealer can tell you the production month of your vehicle.

2 All details relate to the recommended mobile-phone firmware version and are subject to correction. Similar functionality is to be expected from newer versions of the same firmware. This cannot, however, be guaranteed. Should a phone with older firmware not function properly with the universal mobile phone preparation with Bluetooth interface, a newer version of the software should normally offer a solution. To get additional information please visit the mobile phone database on [www.audi.com](http://www.audi.com)

3 These phone adapters are not available with Audi direct help.

4 The phone adapter cannot be used in vehicles built in 2006 and after. Your Audi dealer can tell you the model year of your vehicle.

5 This adapter can only be used in vehicles with Bluetooth<sup>®</sup> interface. Consult the 'Mobile phones tested with Bluetooth<sup>®</sup>' abstracts to find out whether your vehicle has such an interface and which functions are available.

6 Only numbers saved under 'General' are transferred.

8 This mobile phone has only limited functionality when used with a phone adapter. Please consult the adapter manual for more information.

9 iPhone is a trademark of Apple Inc.