

VCDS
Windows Based VAG/VAS Emulator
VCDS Version: Release 12.12.0 Data version: 20130910
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Tuesday, 03, October, 2017, 13:32:22:62939

VIN: WAUZZZ4F38N180585 License Plate:
Mileage: 176170km-109466mi Repair Order:

Chassis Type: 4F (4L0)
Scan: 01 02 03 05 06 07 08 09 0E 15 16 17 18 19 36 37 42 46 47 4F
52 53 55 56 61 62 6D 72 76 77

VIN: WAUZZZ4F38N180585 Mileage: 176170km/109466miles

00-Steering Angle Sensor -- Status: OK 0000
01-Engine -- Status: OK 0000
02-Auto Trans -- Status: Malfunction 0010
03-ABS Brakes -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
06-Seat Mem. Pass -- Status: OK 0000
07-Control Head -- Status: OK 0000
08-Auto HVAC -- Status: OK 0000
09-Cent. Elect. -- Status: OK 0000
0E-Media Player 1 -- Status: Sporadic communication error 1000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: Malfunction 0010
18-Aux. Heat -- Status: OK 0000
19-CAN Gateway -- Status: Malfunction 0010
36-Seat Mem. Drvr -- Status: OK 0000
37-Navigation -- Status: Malfunction 0010
42-Door Elect, Driver -- Status: OK 0000
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: OK 0000
4F-Centr. Electr. II -- Status: OK 0000
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: OK 0000
55-Xenon Range -- Status: OK 0000
56-Radio -- Status: OK 0000
61-Battery Regul. -- Status: OK 0000
62-Door, Rear Left -- Status: OK 0000
6D-Trunk Elect. -- Status: Malfunction 0010
72-Door, Rear Right -- Status: Malfunction 0010
76-Park Assist -- Status: OK 0000
77-Telephone -- Status: OK 0000

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 2

VIN: WAUZZZ4F38N180585 License Plate:

Address 01: Engine Labels: Redir Fail!
Part No SW: 4F5 910 401 S HW: 4F0 907 401 C
Component: 2.7L V6TDI G000CG 0020
Revision: --H05--- Serial number:
Coding: 0011382
Shop #: WSC 02145 785 00200
VCID: 3169F34FA8DC81962BD-8064

No fault code found.
Readiness: 0 0 1 X 1

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 3

VIN: WAUZZZ4F38N180585 License Plate:

Address 02: Auto Trans Labels: 01J-927-156.lbl
Part No SW: 4F5 910 155 R HW: 01J 927 156 JG
Component: V30 0AN 2.7ITDI RdW 0030
Revision: --H06--- Serial number: 000000000000453
Coding: 0000001
Shop #: WSC 04940 001 00001
VCID: 3663C05341B2A6AE7EF-8063

2 Faults Found:

005968 - Supply Voltage

P1750 - 000 - too Low - Intermittent

Freeze Frame:

Fault Status: 00100000
Fault Priority: 0
Fault Frequency: 26
Reset counter: 255
Time Indication: 0
Date: 2064.00.00
Time: 00:00:00

Freeze Frame:

RPM: 96 /min
RPM: 0 /min
(no units): 13.0
Torque: 152.0 Nm
Temperature: 23.0°C
T.B. Angle: 0.0°
Bin. Bits: 0101 0 0

006168 - Pressure Control Valve 2 (N216)

P1818 - 006 - Electrical Malfunction - Intermittent

Freeze Frame:

Fault Status: 00100110
Fault Priority: 0
Fault Frequency: 3
Reset counter: 255
Mileage: 176015 km
Time Indication: 0
Date: 2017.11.10
Time: 08:43:20

Freeze Frame:

RPM: 1120 /min
RPM: 0 /min
(no units): 13.0
Torque: 78.0 Nm
Temperature: 34.0°C
T.B. Angle: 0.0°
Bin. Bits: 0101 0 1

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 4

VIN: WAUZZZ4F38N180585 License Plate:

Address 03: ABS Brakes Labels: 4F0-910-517.lbl
Part No SW: 4F0 910 517 AC HW: 4F0 614 517 T
Component: ESP8 front H01 0070
Revision: 00000000 Serial number: 000000000000000
Coding: 0020876
Shop #: WSC 02145 785 00200
VCID: 65C1571FAC941D36075-8030

No fault code found.

Address 05: Acc/Start Auth. Labels: 4F0-910-852.clb
Part No SW: 4F0 910 852 B HW: 4F0 905 852 D
Component: FBSAUDIC6 ELV H05 0100
Revision: 00H05000 Serial number: 10602601167187
Coding: 0000131
Shop #: WSC 02145 785 00200
VCID: 2541171FEC14DD36C75-8070

Subsystem 1 - Part No: 4F0 910 132 E
Component: FBSAUDIC6 EZS H03 0020

Subsystem 2 - Part No: 4F0 910 220 D
Component: FBSAUDIC6 IDG H01 0040

No fault code found.

Address 06: Seat Mem. Pass Labels: None
Part No SW: 4F0 910 760 HW: 4F0 959 760
Component: Sitzmemory BFS H04 0050
Revision: 00000000 Serial number: 00000000896400
Coding: 0070752
Shop #: WSC 02145 785 00200
VCID: E1C9C30F38BCF1167BD-80B4

No fault code found.

VCDS
Self-Diagnosis Log
Tuesday, 03, October, 2017, 13:32:22:62939
Page 5

VIN: WAUZZZ4F38N180585 License Plate:

Address 07: Control Head Labels: 4F0-910-7xx-07-H.lbl
Part No SW: 4F0 910 732 H HW: 4E0 035 729
Component: Interfacebox H43 5140
Revision: 00000000 Serial number: 350H+087897923
Coding: 0001001
Shop #: WSC 02335 785 00200
VCID: 285F1E2B9B06C05EFC3-807D

Subsystem 1 - Part No: 4F0 910 609 E
Component: Bedienteil MMIC6H01 0060

Subsystem 2 - Serial number: 00000001149299

Subsystem 3 - Serial number: 0114.08.080000000100010301ÿ

Subsystem 4 - Serial number: 010301ÿ

No fault code found.

Address 08: Auto HVAC Labels: 4F0-910-043.lbl
Part No SW: 4F0 910 043 A HW: 4F1 820 043 AG
Component: KLIMABETAETIGUNG30 0020
Revision: 00000054 Serial number: 00000000562606
Coding: 0002326
Shop #: WSC 02145 785 00200
VCID: 1C3732FBDF5E1CFE68B-8049

No fault code found.

Address 09: Cent. Elect. Labels: 4F0-910-279.lbl
Part No SW: 4F0 910 279 N HW: 4F0 907 279
Component: ILM Fahrer H22 0320
Revision: 00000000 Serial number: 4F0907279
Coding: 0012121
Shop #: WSC 02335 785 00200
VCID: 3467FA5B57CEB4BE40B-8061

Subsystem 1 - Part No: 4F1 910 113 C Labels: 1KX-955-119.CLB
Component: Wischer AudiC6 H06 0210
Coding: 00064784
Shop #: WSC 02335

Subsystem 2 - Part No: 8K0 910 557 Labels: 8K0-955-559.CLB
Component: REGENLICHTSENSORH04 0003
Coding: 00211757
Shop #: WSC 02335

No fault code found.

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 6

VIN: WAUZZZ4F38N180585 License Plate:

Address 0E: Media Player 1 Labels: 4E0-910-111.lbl
Part No SW: 4E0 910 110 E HW: 4E0 035 110 A
Component: MP3-Changer H47 0390
Revision: 00047003 Serial number: AUZ5ZBH8563401
Shop #: WSC 00000 000 00000
VCID: 1A3B34E3D56A62CE7A7-804F

No fault code found.

Address 15: Airbags Labels: 4F0-910-655-8R.lbl
Part No SW: 4F0 910 655 E HW: 4F0 959 655 B
Component: 42 AIRBAG AUDI8RH30 0280
Revision: 09H30000 Serial number: 0037LD0ZCDR2
Coding: 0013362
Shop #: WSC 02325 785 00200
VCID: 29591B2F800CF956E3D-807C

Subsystem 1 - Serial number: 6332CSME3F1614382

Subsystem 2 - Serial number: 6342CSME3F1572184

Subsystem 3 - Serial number: 6352QSME50030422-

Subsystem 4 - Serial number: 6362QSME4103282CA

Subsystem 5 - Serial number: 63734SME7A010300M

Subsystem 6 - Serial number: 63834SME6A021228X

No fault code found.

Address 16: Steering wheel Labels: 4F0-910-549.lbl
Part No SW: 4F0 910 549 A HW: 4F0 953 549 D
Component: J0527 0410
Revision: 00H03000 Serial number: 90055082260006
Coding: 0002042
Shop #: WSC 02145 785 00200
VCID: 275D1D179618CF26F59-8072

Subsystem 1 - Part No: XXXXXXXXXXXX

Component: E0221 H02 0030

No fault code found.

VIN: WAUZZZ4F38N180585 License Plate:

Address 17: Instruments Labels: 4F0-920-xxx-17.clb
Part No SW: 4F0 920 934 G HW: 4F0 920 934 G
Component: KOMBIINSTR. 0900
Revision: 00400000 Serial number: AYN21GPDA
Coding: 3072056
Shop #: WSC 38059 136 80234
VCID: 2C57E23B8FFEEC7E18B-8079

2 Faults Found:

00438 - Fuel Supply Sensor 2 (G169)

010 - Open or Short to Plus - Intermittent

Freeze Frame:

Fault Status: 00101010

Fault Priority: 7

Fault Frequency: 2

Reset counter: 184

Mileage: 176171 km

Time Indication: 0

Date: 2017.11.13

Time: 14:22:45

00003 - Control Module

005 - No or Incorrect Basic Setting / Adaptation

Freeze Frame:

Fault Status: 01100101

Fault Priority: 6

Fault Frequency: 1

Reset counter: 144

Mileage: 176171 km

Time Indication: 0

Date: 2017.11.13

Time: 14:22:48

Address 18: Aux. Heat Labels: None
Part No SW: 4F0 910 105 A HW: 4F0 265 081 AA
Component: Heizgeraet H08 0100
Revision: B Serial number: 09018641
Coding: 0000111
Shop #: WSC 02145 785 00200
VCID: 1B3531E7DA501BC6611-804E

No fault code found.

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 8

VIN: WAUZZZ4F38N180585 License Plate:

Address 19: CAN Gateway Labels: 4L0-910-468.lbl
Part No SW: 4L0 910 468 A HW: 4L0 907 468 B
Component: J533_Gateway H06 0060
Revision: 00H06000 Serial number: 1100B08814007E
Coding: F5D9BF7730320600
Shop #: WSC 02145 785 00200
VCID: 2D51EF3FB4E4E5760F5-8078

1 Fault Found:

02076 - Media Player Position 1 (R118)

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100

Fault Priority: 3

Fault Frequency: 1

Reset counter: 184

Mileage: 176171 km

Time Indication: 0

Date: 2017.11.13

Time: 13:54:07

Address 36: Seat Mem. Drvr Labels: None
Part No SW: 4F0 910 760 HW: 4F0 959 760
Component: Sitzmemory FS H04 0050
Revision: 000000000 Serial number: 00000000896400
Coding: 0066658
Shop #: WSC 02145 785 00200
VCID: E1C9C30F38BCF1167BD-80B4

No fault code found.

VIN: WAUZZZ4F38N180585 License Plate:

Address 37: Navigation Labels: 4E0-910-88x-37.lbl
Part No SW: 4E0 910 888 P HW: 4E0 919 887 M
Component: MNS ECE H52 1060
Revision: 00000000 Serial number: 364HR087811324
Shop #: WSC 38059 136 59414
VCID: 3B75D1677A907BC6811-806E

2 Faults Found:

00446 - Function Limitation due to Under-Voltage

002 - Lower Limit Exceeded - Intermittent

Freeze Frame:

Fault Status: 00100010

Fault Priority: 7

Fault Frequency: 16

Reset counter: 184

Mileage: 174850 km

Time Indication: 0

Date: 2017.09.25

Time: 09:06:07

Freeze Frame:

Hex Value: 0x5A09

Hex Value: 0x5B94

Hex Value: 0x0047

02927 - DVD Read Error

000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000

Fault Priority: 6

Fault Frequency: 5

Reset counter: 147

Mileage: 175211 km

Time Indication: 0

Date: 2017.10.09

Time: 07:15:21

Freeze Frame:

Hex Value: 0x59DC

Hex Value: 0x7901

Hex Value: 0x02FF

Hex Value: 0x0204

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 10

VIN: WAUZZZ4F38N180585 License Plate:

Address 42: Door Elect, Driver Labels: 4F0-910-793-42.lbl
Part No SW: 4F0 910 793 E HW: 4F0 959 793 E
Component: TSG FA H12 0210
Revision: 00000000 Serial number: `y,l
Coding: 0001770
Shop #: WSC 02327 785 00200
VCID: 2C57E23B8FFEEC7E18B-8079

No fault code found.

Address 46: Central Conv. Labels: 4F0-910-289.lbl
Part No SW: 4F0 910 289 K HW: 4F0 907 289 K
Component: Komfortgeraet H27 0220
Revision: 02200027 Serial number: 01131763780000
Coding: 3287793
Shop #: WSC 02335 785 00200
VCID: 326BFC43ADDABA8E527-8067

Subsystem 1 - Part No: 1K0 951 605 C
Component: LIN BACKUP HORN H03 1301

Subsystem 2 - Part No: 4F0 910 177
Component: Innenraumueberw.H01 0020

1 Fault Found:

01504 - Bulb for License-Plate Light (X)
009 - Open or Short to Ground
Freeze Frame:
Fault Status: 01101001
Fault Priority: 3
Fault Frequency: 64
Reset counter: 144
Mileage: 174842 km
Time Indication: 0
Date: 2017.09.23
Time: 16:42:18

Address 47: Sound System (J525) Labels: Redir Fail!
Part No SW: 4F0 910 223 M HW: 4F0 035 223 N
Component: Amp.-ASK-RD H07 0270
Revision: S1400000
Coding: 020001
Shop #: WSC 02399 823 56573
VCID: 285F1E2B5B06C05EFC3-807D

No fault code found.

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 11

VIN: WAUZZZ4F38N180585 License Plate:

Address 4F: Centr. Electr. II Labels: 4F0-910-280.lbl
Part No SW: 4F0 910 280 HW: 4F0 907 280 A
Component: ILM Beifahrer H12 0100
Revision: Serial number: 00000000576291
Coding: 0001103
Shop #: WSC 02335 785 00200
VCID: DEB3F8F309C2CEEE46F-808B

No fault code found.

Address 52: Door Elect, Pass. Labels: 4F0-910-793-52.lbl
Part No SW: 4F0 910 793 E HW: 4F0 959 792 E
Component: TSG BF H12 0210
Revision: 00000000 Serial number: #%,|
Coding: 0001770
Shop #: WSC 02327 785 00200
VCID: 2C57E23B8FFEEC7E18B-8079

No fault code found.

Address 53: Parking Brake Labels: 4F0-910-801.clb
Part No SW: 4F0 910 801 C HW: 4F0 907 801 A
Component: EPB CDEC0080 H04 0080
Revision: --H04---
Coding: 0000531
Shop #: WSC 02145 785 00200
VCID: 204F060BF336381EB43-8075

No fault code found.

Address 55: Xenon Range Labels: 8P0-907-357.lbl
Part No: 8P0 907 357 H
Component: Dynamische LWR H02 0010
Revision: 00000001 Serial number:
Coding: 0000003
Shop #: WSC 02325 785 00200
VCID: 3F8DA5776E8867E6AD9-806A

No fault code found.

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 12

VIN: WAUZZZ4F38N180585 License Plate:

Address 56: Radio Labels: 4E0-910-541.lbl
Part No SW: 4E0 910 541 Q HW: 4F0 035 541 L
Component: TUNER EU/US/RDW H42 0620
Revision: 00000000 Serial number: 394H1087927663
Coding: 0000001
Shop #: WSC 02145 785 00200
VCID: 2E53E833B9E29E6E36F-807B

No fault code found.

Address 61: Battery Regul. Labels: 4F0-910-181.lbl
Part No SW: 4F0 910 181 F HW: 4F0 915 181 B
Component: J0644 BEM H12 0760
Revision: 00000000 Serial number: 00000000136664
Shop #: WSC 00000 384 00290
VCID: 24470A1BE72E243ED0B-8071

Subsystem 1 - Part No: 4F0 915 105 E
Component: von VA0 JCB3F790DZ
Coding: 34463039313531303545205641304A43423346373930445A
Shop #: WSC 12345 384 00290

No fault code found.

Address 62: Door, Rear Left Labels: 4F0-910-795.lbl
Part No SW: 4F0 910 795 E HW: 4F0 959 795 E
Component: TSG HL H21 0210
Coding: 0001066
Shop #: WSC 02327 785 00200
VCID: 2E53E833B9E29E6E36F-807B

No fault code found.

VIN: WAUZZZ4F38N180585 License Plate:

Address 6D: Trunk Elect. Labels: Redir Fail!
Part No SW: 4F9 910 591 HW: 4F9 827 851 F
Component: ValeoHeckdeckel H25 0290
Revision: --H25001 Serial number: E5030000B
Shop #: WSC 98765 666 38354
VCID: ECD7A23BCF7EAC7ED8B-80B9

Subsystem 1 - Part No: 4F9 910 592
Component: ValeoHeckdeckel H25 0290

Subsystem 2 - Serial number: E5030100B

Subsystem 3 - Serial number: RD26.08.08--H25001001A0089ÿ

Subsystem 4 - Serial number: 1A0089ÿ

2 Faults Found:

02072 - Control Module for Energy Management (J644)

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100
Fault Priority: 3
Fault Frequency: 16
Reset counter: 184
Mileage: 175841 km
Time Indication: 0
Date: 2017.11.04
Time: 16:02:31

02786 - Module 2 for Hatch / Trunk Lid (J756)

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100
Fault Priority: 3
Fault Frequency: 3
Reset counter: 154
Mileage: 174842 km
Time Indication: 0
Date: 2017.09.23
Time: 16:39:34

VCDS
Self-Diagnosis Log
Tuesday,03,October,2017,13:32:22:62939
Page 14

VIN: WAUZZZ4F38N180585 License Plate:

Address 72: Door, Rear Right Labels: 4F0-910-795.lbl
Part No SW: 4F0 910 795 E HW: 4F0 959 794 E
Component: TSG HR H21 0210
Coding: 0001066
Shop #: WSC 02327 785 00200
VCID: 2E53E833B9E29E6E36F-807B

1 Fault Found:

02115 - Locking Unit for Central Locking

008 - Implausible Signal

Freeze Frame:

Fault Status: 01101000

Fault Priority: 3

Fault Frequency: 1

Reset counter: 144

Mileage: 176171 km

Time Indication: 0

Date: 2017.11.13

Time: 13:53:07

Address 76: Park Assist Labels: 4Fx-910-283.lbl
Part No SW: 4F0 910 283 F HW: 4F0 919 283 F
Component: Parkhilfe 4-Kan H09 0060
Revision: 00H09000 Serial number: 06240823802722
Coding: 0201116
Shop #: WSC 02145 785 00200
VCID: 275D1D179618CF26F59-8072

No fault code found.

Address 77: Telephone Labels: 4F1-910-336.lbl
Part No SW: 4F1 910 336 C HW: 4F1 862 335
Component: BTA H11 0960
Revision: 00H11000 Serial number: 00000007589069
Coding: 0050011
Shop #: WSC 02335 785 00200
VCID: 24470A1BE72E243ED0B-8071

No fault code found.

End -----