

## SVM Codes Nachrüstung Anhängerkupplung VAG:

### SVM codes retrofitting trailer hitch VAG:

#### VW:

VW Golf VII, Golf VII Variant (AU), fixed 37A58  
VW Golf VII, Golf VII Variant (AU), removable 37A6C  
VW Golf VII, Golf VII Variant (AU), with preparation, 37A70  
VW Golf VII Sportsvan, fixed 39C8E  
VW Golf VII Sportsvan, removable 39C92  
VW Golf Plus / Cross, 30F2D  
VW Golf VI, Golf VI Variant, 30F2D  
VW Golf VI Convertible, 355B4  
VW Golf V, Golf V Variant, 30F2D  
VW Jetta (A6) 2011>>, 34CBC  
VW Jetta (A5) >>2011, 30F2D  
VW EOS, all years of production, 30F2D

**VW Passat B8 (3G) 40/2014 >>: SVM No longer possible (since 01.01.2016)! License coding!**

(VW Passat B8 (3G), fixed 3B497)

(VW Passat B8 (3G), removable 3B46B)

VW Passat B7, fixed, 36156

VW Passat B7, removable, 361BA

VW Passat CC >>CW 45/11, 30F2D

VW Passat CC CW 45/11>>, 345F1

**VW Arteon 2017>>, SVM Not possible! License coding!**

**VW T-Roc (a1) 2017>>, SVM Not possible! License coding!**

**VW Polo 10/17>>, SVM Not possible! License coding!**

VW Polo (6C) CW 22 05/14>>, fixed 39ED4

VW Polo (6C) CW 22 05/14>>, removable 39EFC

VW Polo (6R) A05 MY2009>>, 30F2D / **302F1 ?**

VW T5 GP / T6 (7E) fixed, 30CB4

VW T5 GP / T6 (7E) removable, 30D3B

**VW Touran II (5T), CW 32/2015>>, SVM Not longer possible! License coding!**

VW Touran (1T), MY2012>>, 345C6

VW Touran, >>MY2011, 30F2D

**VW Tiguan II (AD), CW 06/2015>>, SVM Not longer possible! License coding!**

VW Tiguan (5N), >> CW 05/2015, 30F2D

VW Amarok, 2010>> fixed, with preparation 31495 (Login EPH 71679 contained in ETKA)

VW Phaeton GP2 & GP3 359AC

VW Touareg GP, fixed 35FDF

VW Touareg GP, removable 35FE3

(VW Touareg AUS 35EB4)

(VW Touareg NAR 3635C)

VW Sharan / Seat Alhambra MY 2010>>, fixed, 37273

VW Sharan / Seat Alhambra MY 2010>>, removable, 37287

VW Crafter (SY / SZ) / MAN TGE (UY / ZU) 01/2017>>, with preparation (PR: 1M5), not necessary because module is already installed

VW Crafter (SY / SZ) / MAN TGE (UY / ZU) 01/2017>>, with preparation (PR: 1D7), not necessary because module is already installed

VW Crafter (SY / SZ) / MAN TGE (UY / ZU) 01/2017>>, without preparation (PR: 1D0), not known yet

VW Crafter (SY / SZ) / MAN TGE (UY / ZU) 01/2017>>, remove e-kit (PR: 1D1), not known yet

VW Crafter (2E / 2F) >>12/2016, with preparation (PR: 1M5), 30788 (without €)

VW Crafter (2E / 2F) >>12/2016, with preparation (PR: 1D7), No coding required, module is already installed !

VW Crafter (2E / 2F) >>12/2016, without preparation (PR: 1D0), 3079C (€)

VW Crafter (2E / 2F) >>12/2016, remove e-kit (PR: 1D1), 307AC (€)

## Seat:

Seat Arona (KJ) 11/17>>, without / with preparation (PR: 1D0 / 1D8), KJ69

Seat Ibiza 06/17>>, without / with preparation (PR: 1D0 / 1D8), KJ69

Seat Leon (5F/KC), without / with preparation (PR: 1D0 / 1M5), DA69AHV or DA69AHV123

Seat Leon (5F/KC), with preparation (PR: 1D8), No coding required, module is already installed !

Seat Ateca (5F), without / with preparation (PR: 1D0 / 1M5), [331D](#)

Seat Ateca (5F), with preparation (PR: 1D8, [1M7](#)), No coding required, module is already installed !

Seat Exeo (3R) 2010>>, 30F2D

Seat Alhambra (7N) MY 2011>>, 3211

Seat Alhambra (7M/7V) MY 2010, fixed, 37273

Seat Alhambra (7M/7V) MY 2010, removable, 37287

Seat Toledo (NH) 2014>>, 328A

## Skoda:

[Skoda Karoq 09/17>>, SVM Not possible! License coding!](#)

Skoda Octavia III (5E/NE) without preparation (PR: 1D0), 30E3E (~~old 30AD6~~)

Skoda Octavia III (5E/NE) with preparation (PR: 1D7, 1D8), 30F05

Skoda Superb (3T/3V/NP) 06/2015>> without preparation (PR: 1D0) 33089

Skoda Superb (3T/3V/NP) 06/2015>> with preparation (PR: 1D7) 33075

(Skoda Superb 06/15>> only to OE swiveling trailer hitch (PR: 1D4), without preparation (PR: 1D0) 329FA)

(Skoda Superb 06/15>> only to OE swiveling trailer hitch (PR: 1D4), with preparation (PR: 1D7) 32A22)

Skoda Kodiak (NS), without preparation (PR: 1D0 to PR: 1M6 (swiveling trailer hitch)) 33904, [please note SKODA service](#)

[info about "with electric tailgate" use 342E5](#)

Skoda Kodiak (NS), with preparation (PR: 1M5 to PR: 1M6 (swiveling trailer hitch)) 33904, [please note SKODA service](#)

[info about "with electric tailgate" use 342E5](#)

Skoda Fabia III (6C/NJ/55), without preparation (PR: 1D0), 32122

Skoda Fabia III (6C/NJ/55), with preparation (PR: 1D7), 32136

Skoda Rapid, Rapid Spaceback (NA/NH), 25.05.2015>>, without preparation (PR: 1D0), 325AA

Skoda Rapid, Rapid Spaceback (NA/NH), 25.05.2015>>, with preparation (PR: 1D7), 325BE

[Skoda Rapid, Rapid Spaceback \(NA/NH\), >>25.05.2015, without preparation \(PR: 1D0\), 31584](#)

[Skoda Rapid, Rapid Spaceback \(NA/NH\), >>25.05.2015, with preparation \(PR: 1D7\), 31598](#)

Skoda Yeti (5L) MY 2014>>, without preparation (PR: 1D0), 31B8B

Skoda Yeti (5L) MY 2014>>, with preparation (PR: 1D7), 31B9F

## Audi:

Audi A1 (8X), 050200

Audi A3 (8V), full cooler fan or with preparation (PR: 1M5) 050203 / reduced cooler fan 050204

(Audi A3 (8V), only to OE swiveling trailer hitch, full cooler fan or with preparation (PR: 1M5) 050209 / reduced cooler fan 050205)

Audi A3 8V, Limousine – SVM unknown, → VCDS

Audi A3 (>> 8P), 050200

[Audi A4 B9 \(8W/F4\), SVM Not possible! License coding!](#)

Audi A4 B8 (8K/FL), 050200 !Only with correct cooler fan performance or PR: 1D8! / (3.0 TDI), [050204](#)

Audi A4 B7 (8E), 10/2004>>, 30F2D

Audi A5 (8T/FR/N/F5) MY 2010>>, 050200 !Only with correct cooler fan performance or PR: 1D8! / (3.0 TDI), 050204

Audi A6 C6/C7 (4F/FB/4G), 050200 !Only with correct cooler fan performance or PR: 1D8! / (3.0 TDI), 050205, [050203](#)

Audi A7 (4G/FC) MY 2010>>, 050200 !Only with correct cooler fan performance or PR: 1D8! / (3.0 TDI), 050205

[Audi Q2 \(GA\), SVM Not possible! License coding!](#)

Audi Q3 (8U/FS), 050200 !Only with correct cooler fan performance or PR: 1D8!

[Audi Q5 \(FY/N\), SVM Not possible! License coding!](#)

Audi Q5 (8R), 050200 !Only with correct cooler fan performance or PR: 1D8! / (3.0 TDI), 050205

[Audi Q7 \(4M\), SVM Not possible! License coding!](#)

Audi Q7 (4L/FE), 050200 !Only with correct cooler fan performance or PR: 1D8!

#### ODIS- Diagnosetester starten

- Funktion „Diagnose“ starten
- „Sonderfunktionen“ auswählen
- Unterpunkt „SW anpassen“ auswählen
- Mit „Prüfung durchführen“ bestätigen
- Über Button „Um-/ Nachrüstlösungen“ auswählen
- nur bei SEAT „Software aktualisieren über Massnahmengcode“ auswählen

**Yellow:** Change

**Green:** New

**Red:** Delete

MY: Model year

CW: Calendar week

PR: Equipment code

GP: Große Modellpflege

(€): for using SVM Code must payd