

## Overview valve/seat problems <100.00 km



Based on practical experiences, Prins has compiled a list of vehicles in which problems with valves/valve seats (excessive wear) may occur at a a low mileage (<100,000 km). This list is updated regularly. To keep this list up-to-date, Prins is asking their clients to report any valve/valve seat problems (service@prins.eu).

A base d'expériences sur le marché, Prins a établi une liste des véhicules susceptibles d'avoir des problèmes avec les soupapes/sièges de soupape à un kilométrage réduit (<100.00 km) (usure excessive). Cette liste est mise à jour régulièrement. Afin de tenir cette liste à jour, Prins demande ses clients de bien vouloir signaler des problèmes de soupapes/sièges de soupape (service@prins.eu).

Op basis van ervaringen uit de markt heeft Prins een lijst samengesteld waarin voertuigen staan vermeld die bij een geringe kilometerstand (<100.000 km) problemen met kleppen/klepzittingen kunnen krijgen (overmatige slijtage). Deze lijst wordt regelmatig bijgewerkt. Om deze lijst up-to-date te houden vraagt Prins zijn klanten om klep/klepzitting problemen te melden (service@prins.eu).

Auf der Grundlage von Erfahrungen aus dem Markt hat Prins eine Liste mit Fahrzeugen zusammengestellt, die bei einer geringen Kilometerzahl (< 100.000 km) Probleme mit den Ventilen/Ventilsitzen bekommen können (übermäßiger Verschleiß). Diese Liste wird regelmäßig aktualisiert. Damit diese Liste ständig aktuell ist, bittet Prins ihre Kunden, Ventil/Ventilsitz-Probleme zu melden (service@prins.eu).

Brand	Model	Year of construction	Engine code	Engine capacity	Edition	Problem description	Solution	Remarks	Information source (Prins or customer)
Audi	Different types		BSE	1600 cc		Excessive wear of valves/seats		Cylinderhead Mexico	Customer
Auui	Dillerent types		DOL	1000 CC		Excessive wear or varves/sears		Cyllindernead Mexico	Customer
Cadilax	Escalade	2000>		6000 cc 16V		Excessive wear of valves/seats			Customer
Cuanax	Ecodidae	2000		0000 00 101		Excessive wear or varyour coats			Cactomer
Chevrolet	All models	1998>				Excessive wear of valves/seats			Customer
Chevrolet		1998>	Vortec			Excessive wear of valves/seats		Even problems with flash lube	Customer
Citroen	Berlingo	1998>	LFX	1800 cc 8V		Excessive wear of valves/seats			Customer
Citroen	Xantia	1998?	LFX	1800 cc 8V		Excessive wear of valves/seats			Customer
Citroen	C1	2005>		1000 cc 12V		Excessive wear of valves/seats			Customer
Daewoo	Tacuma	2000>		2000 cc 8V		Excessive wear of valves/seats			Prins
Dacia	Logan	2006>		1400 cc 8V		Excessive wear of valves/seats			Customer
Dacia	Logan	2006>	K7M710	1600 cc 8V		Excessive wear of valves/seats			Customer
Daihatsu	Terios	2001>	K3-VE	1300 cc 16V		Excessive wear of valves/seats			Customer
Daihatsu	YRV	2001>	K3-VE	1300 cc 16V		Excessive wear of valves/seats			Customer
Dodge	Ram 1500/2500	2002>		4700 cc 16V		Excessive wear of valves/seats			Customer
Dodge	Caliber	2006>		1800 cc 16V		Excessive wear of valves/seats			DCNL
Dodge	Caliber	2006>		2000 cc 16V		Excessive wear of valves/seats			DCNL
Ford	Focus	1998>		1800 cc		Excessive wear of valves/seats			Customer
Ford	Fiesta	11-2002>	A9JA	1300 cc 8V		Excessive wear of valves/seats		After 20.000 km	Customer
Ford	Mondeo	1998>		1800 cc		Excessive wear of valves/seats			Customer
Ford	Ka			1250 cc		Excessive wear of valves/seats			Customer
Ford	Explorer	1993-1998		4000 cc 12V		Excessive wear of valves/seats		Exhaust valves	Customer
Ford	Windstar	1995		3000 cc 12V		Excessive wear of valves/seats		Exhaust valves	Customer
Honda	All models	2003>				Excessive wear of valves/seats			Customer
Hyundai	Sonata	2005>	G4KC	2400 cc 16V		Excessive wear of valves/seats			Customer
Hyundai	Trajet	2000-2004	G4JP	2000 cc 16V		Excessive wear of valves/seats			Prins
Hummer	All models					Excessive wear of valves/seats			Customer
Infinity	FX35	2003>		3500 cc 24V		Excessive wear of valves/seats			Customer
Jeep	Grand Cherokee	1999-2005		4700 cc 16V		Excessive wear of valves/seats			Customer/Importer
Lexus	RX300	2001>	1MZ-FE	3000cc 24V		Excessive wear of valves/seats			Customer
Mazda	Mazda 6	2002>	All ford engines	1		Excessive wear of valves/seats		All Ford engines!!!	Customer
Mazda	Tribute	2001-2004	MOT.YF	2000cc 16V 1250 cc		Excessive wear of valves/seats Excessive wear of valves/seats			Customer Customer
Mazda	121								



## Overview valve/seat problems <100.00 km



Mercedes	A-class	2005>	All engines	1500/1700/2000/T (8V)	Excessive wear of valves/seats			Customer
Mercedes	B-class	2005>	All engines	1500/1700/2000/T (8V)	Excessive wear of valves/seats	Fit special LPG cylinderhead original Mercedes		Customer
Mercedes	Vaneo	2004-2005		1900 cc	Excessive wear of valves/seats	Morocaco		Customer
	0.11	0004		0.400 401/				
Mitsubishi Mitsubishi	Outlander	2001>		2400 cc 16V	Excessive wear of valves/seats			Importer
Mitsubishi	Grandis	2004>		2400 cc 16V	Excessive wear of valves/seats			Customer
Nissan	Maxiam QX	1995>		3000 cc	Excessive wear of valves/seats			Customer
Vissan	Primera	1998>	All engines	0000 00	Excessive wear of valves/seats			Customer
Nissan	X-Trail	2003>		2000 cc 16V	Excessive wear of valves/seats			Customer
Vissan	350 Z	2004-		3500 cc 24V	Excessive wear of valves/seats			Customer
Vissan	Murano	2004-		3500 cc 24V	Excessive wear of valves/seats			Customer
Opel	All models	2004>	Z18XE	1800 cc 16V	Excessive wear of valves/seats			Customer
Opel	All models	2004>	Z20ZE	2000 cc 16V	Excessive wear of valves/seats			Customer
Opel	All models	2005>	Z16XEP	1600 cc 16V	Excessive wear of valves/seats			Customer
Opel	All models	2005>	Z18XER	1800 cc 16V	Excessive wear of valves/seats			Customer
Pougoot	406	1998>	LFX	1800 cc 8V	Excessive wear of valves/seats			Customer
Peugeot Peugeot	Boxer	1998>	XU10J2/RFW	2000 cc 8V	Excessive wear of valves/seats  Excessive wear of valves/seats	1		Peugeot NL
Peugeot Peugeot	Partner	1995>	LFX	1800 cc 8V	Excessive wear of valves/seats  Excessive wear of valves/seats	1		Customer
Peugeot	107	2005>		1000 cc 3V	Excessive wear of valves/seats	<u> </u>		Customer
- agoot		1		1300 00 121	Excessive wear of varyour outs			2 00.0
Pontiac	Trans Sport	1993-1997	Quad 4	2300 cc 16V	Excessive wear of valves/seats			Customer
Porsche	Cayenne	2004>		3200 cc 24V	Excessive wear of valves/seats			Customer
Porsche	Cayenne S	2004>		4500 cc 32V	Excessive wear of valves/seats			Customer
Renault	Laguna	1994-1998		2000 cc 8V	Excessive wear of valves/seats			Prins
Renault	Espace	1994-1998		2000 cc 8V	Excessive wear of valves/seats			Customer
Renault	Espace IV	2002-		3500 cc 24V	Excessive wear of valves/seats			Customer
Renault	Vel Satis	2002-		3500 cc 24V	Excessive wear of valves/seats			Customer
Renault	Megane 2	2002-		1600 cc 16V	Excessive wear of valves/seats		inlet+exhaust valves	Customer
Renault	Kangoo	1998-		1400 cc 8V	Excessive wear of valves/seats		Inlet valves	Customer
Saab	9- versions	1998>	16V		Excessive wear of valves/seats			Customer
Jaau	3- VELSIONS	1990>	100		Excessive wear or valves/seats			Customer
Seat	Alhambra	2000>	ATM	2000 cc 8V	Excessive wear of valves/seats			Prins
	/ undinibila	20002	,,,,,,	2000 00 01	Excessive wear or varyed at			7 71110
Skoda	Fabia	2000>	AZL	2000 cc 8V	Excessive wear of valves/seats		inlet valves 120.000 km	Customer
Smart	Forfour	2004>		1100/1300/1500	Excessive wear of valves/seats		(2 reports from NL)	Customer
Siliait	Folloui	2004>		cc (12V)	Excessive wear or valves/seats		(2 reports from NL)	Customer
Suzuki	Liana	2004>		1600 cc 16V	Excessive wear of valves/seats			Customer
		1000		1				
oyota	All models	1996>	VVTI	All models	Excessive wear of valves/seats	<del> </del>	Drobleme even with Book hit	Customer
Toyota Toyota	Corolla	2004> 2005>	VVII	1000 cc 12V	Excessive wear of valves/seats		Problems even with flash lube	Customer Customer
oyota	Aygo	2000>		1000 CC 12V	Excessive wear or varves/sears			Customer
				+		Fit special CNG cylinderhead original		
		2000>	ATM	2000 cc 8V	Excessive wear of valves/seats	Volkswagen		Customer
/olkswagen	Sharan	2003>		3200 cc 24V	Excessive wear of valves/seats	nagon		Customer
		2003>	1			Fit special CNG cylinderhead original	Cultin doub and Maritim	
/olkswagen	Touareg	2003>	A 3/ A			Volkswagen	Cylinderhead Mexico	Customer
/olkswagen			AXA	2000 cc 8V	Excessive wear of valves/seats	VOIKSWageri		
/olkswagen /olkswagen	Touareg	2002>	BKL	3200 cc 24V	Excessive wear of valves/seats	voikswageri		Customer
/olkswagen /olkswagen /olkswagen	Touareg T5 Phaeton Golf		BKL BUB	3200 cc 24V 3200 cc 24V	Excessive wear of valves/seats Excessive wear of valves/seats	voikswagen		Customer Customer
/olkswagen /olkswagen /olkswagen /olkswagen	Touareg T5 Phaeton	2002>	BKL	3200 cc 24V	Excessive wear of valves/seats	Voikswageri	Cylinderhead Mexico	
/olkswagen /olkswagen /olkswagen /olkswagen /olkswagen	Touareg T5 Phaeton Golf Different types	2002> 2005>	BKL BUB BSE	3200 cc 24V 3200 cc 24V 1600 cc	Excessive wear of valves/seats Excessive wear of valves/seats Excessive wear of valves/seats	VOIRSWAGERI	Cylinderhead Mexico	Customer Customer
/olkswagen /olkswagen /olkswagen /olkswagen /olkswagen	Touareg T5 Phaeton Golf Different types XC90	2002> 2005> 2003>	BKL BUB BSE Turbo	3200 cc 24V 3200 cc 24V 1600 cc 2500 cc turbo	Excessive wear of valves/seats Excessive wear of valves/seats Excessive wear of valves/seats Excessive wear of valves/seats	VOIRSWAGEIT	Cylinderhead Mexico	Customer Customer Customer
Volkswagen Volkswagen Volkswagen Volkswagen Volkswagen Volkswagen Volvo Volvo	Touareg T5 Phaeton Golf Different types	2002> 2005>	BKL BUB BSE	3200 cc 24V 3200 cc 24V 1600 cc	Excessive wear of valves/seats Excessive wear of valves/seats Excessive wear of valves/seats	VOIKSWAGEIT	Cylinderhead Mexico  Problems even with flash lube	Customer Customer