



Maintenance Report

Vehicle: 1991 Buick Park Avenue

VIN: 1G4CW53L3M1703649

Mileage: 156,327.3

Date: April 18, 2019

Component/Step	Treatment/State	ACDelco #	Remarks
Windshield Wiper System			
Fluid	☐ too low ☐ minimum ☒ acceptable ☐ maximum ☐ too high ☐ filled ☒ changed ☐ regular ☒ antifreeze		3.79 liters, 4 quarts
Freeze Protection	☒ checked -30 ☒ °C ☐ °F		
Pump Pressure	☒ checked ☒ aging		
Pipes and Connectors	☒ checked ☐ aging		
Nozzles	☒ checked ☒ cleaned		Not adjustable
Blades	☐ checked ☐ cleaned ☒ replaced	8-2221	560 mm, 22", both sides, pin lock
Windshield	☒ checked ☒ chips 0 ☒ cracks 1		
Air Inlet Screen/Cowl and Drains	☒ checked ☒ cleaned		

Engine Oil			
Oil	☐ too low ☐ minimum ☒ acceptable ☐ maximum ☐ too high ☒ changed ☐ filled ☒ semi ☒ synthetic ☐ conventional ☐ 0W ☐ 5W ☒ 10W ☐ 15W ☐ 20W ☒ 30 ☐ 40 ☐ 50 ☐ 60		SAE 10W-30 or 5W-30 only API SG specification 4.26 liters, 4.5 quarts
Condition	☐ amber ☐ red ☐ brown ☒ black ☐ clear ☐ particles ☐ milky ☐ thick ☐ sludge		
Filter	☒ replaced ☐ reused	PF47, PF52	
Drain Plug Gasket	☒ replaced ☐ reused	14090908	40 N-m, 30 lbf-ft, SAE 9/16"
Life Module	☒ reset ☐ not equipped		

Engine Coolant			
Coolant	☐ too low ☐ minimum ☐ acceptable ☒ maximum ☐ too high ☐ changed ☐ filled ☐ flushed ☐ radiator only ☐ reservoir only ☐ seal tabs added		GM 1825-M specification 12.3 liters, 13 quarts
Condition	☒ clear ☐ aging ☐ dirty or rusty ☒ oily ☐ sludge		
Freeze Protection	☒ checked -50+ ☒ °C ☐ °F		-37 °C, -34 °F
Filler Cap	☐ checked ☐ cleaned ☒ replaced	RC27	15 psi
Filler Cap Pressure	☒ checked 15 psi		14 to 18 psi
System Pressure	☒ checked ☐ leaking (see Notes)		Do not exceed 20 psi
Pipes, Hoses and Clamps	☒ checked ☐ aging		
Pump	☐ checked ☐ replaced	251-718	
Radiator and A/C Condenser	☒ cleaned		

Engine Accessory Drive Belt			
Belt	☐ checked ☒ replaced	6K1025	20.5 x 2595 mm, code SEC
Idler/Tensioner Pulley	☐ checked ☐ replaced	38027	50 N-m, 37 lbf-ft, 18 mm, CCW

Automatic Transmission Fluid			
Fluid	☐ too low ☐ minimum ☒ acceptable ☐ maximum ☐ too high ☒ changed ☐ filled ☐ flushed ☒ pan drop only ☐ Dexron II D ☐ II E ☐ III F ☐ III G ☒ III H ☐ IV J		5.68 liters, 6 quarts (filter change) 10.41 liters, 11 quarts (dry)
Condition	☒ red ☒ brown ☐ black ☒ clear ☐ particles ☐ milky		
Filter	☒ replaced ☐ reused	24227477	
Filter Seal	☐ replaced ☒ reused	08656613	
Pan Gasket	☐ reused ☒ replaced	24204624	17 N-m, 13 lbf-ft, 10 mm